Certificate of Location of Government Corner

ID#:531605 **Description:** SEC COR 16 17 20 21 53 **Date Set:** 8/9/2011 **County:** Olmsted

Section: 16 **Township:** 105N **Range:** 13W **Monument Description:** Cast iron cap on telspar pipe

Reference Ties:

County Survey Disk in E side Blazed 13" Oak N 2° W 45.06'
County Survey Disk in W side Blazed 9" Oak S 2°W 34.40'
Post w/sign 2' north
This corner is located by GPS reference stations "Larry A & B"

Corner History:

1854 Gov't Notes M.G. Karrick 80.00 set post for cor to section. Erected mound at rock. Bur Oak 12 S 45 E 230. White pine 12 S 33 W 157.

11-1883 T. Hunter (P386 No.377) found stake set by Bearing trees in former survey (unrecorded) 1859. 1/16 West found stake set M & L 20.50 (1353.0') set Hunter 1859 an unrecorded survey. South set stake on line to E 1/4 20, 27 chs N of E 1/4 20.

4-1895 W. Fraser (P565 No.518) could not find Hunters stake and Bearing trees. Did not place corner in one spot within 2 rods. Run line South from stake claimed set by Hunter 5 chains North of original corner. This placed it exactly at SW BT S33° W 157 lks. (103.6' 93.72'). Drove stake and renewed notes on SE BT S 27° E 142 lks. original notes of this tree. S 45° E 230 lks. 1/16 East set stake 20.00 M & L to stake found. North set stakes 10.03 then 5.01 1/2 then 5.01 1/2.

12-1939 J. Kerr found 3/4" Bridge bolt packed in Rock and left as found. RPs-Center of 12" Burr Oak N 10°40' W 44.7 ft, center of 10" burr oak S 83°30' W 6.3 ft.
Center of 7" burr oak S 8° E 34.4 ft.

4-6-1972 County Surveyor found J. Kerr iron and remains of original white pine witness tree 12" W pine S33W 157 lks. 103.6 with some original marks. Also found large oak with huge hollow blaze South which would bring corner 10' S of J. Kerr iron.

4-19-1972 County Surveyor measured West from S 1/4 16, no sign of post spoken of in J. Kerr survey 11-1939 but massive conc and shaft corner. North side of apparenct lane or road West set nail 50' E will dig around where 1' rotted off post was supposed to be. Meas West to iron at SW 16 2637.0. Set 40d in ditch bottom at 1300 on chainage line 20' ± N of fence. Also nail at 1320 in road. Did not run line took transit shots from J. Kerr road to witness trees. Found sodded over rotted post used by J. Kerr as 1/4 16-21. (4-20-72 ran and meas line N found some of J. Kerr corners B 26 P 51).

7-1979 County Surveyor set sign post 1.8' North of Monu. (Kerr's Iron Bolt). New RPs-Spk & Co. Surv. Disc in E Side Blazed 13" oak N 2° W 45.06', Spk & Co. Surv. Disc in W. Side Blazed 9" oak S 2°W 34.40', Spk & County Surveyor Disc in N. Side 11" Oak - N 87° W 6.07'.

1-6-1993 V. Fangman found and used Iron Bolt in survey of NE 1/4 section 20.

5-16-2001 McGhie & Betts found and used 1" bolt for survey in SW 1/4 section 16.

12-2-2002 County Surveyor found 3/4" iron bolt up 0.3' in good condition. Replaced sign & post 2.0' North of monument. Did not check ties.

8-9-2011 County survey crew found 3/4" bridge bolt in good condition. Removed and replaced with a 3.5' telspar square pipe with cast iron cap.