Certificate of Location of Government Corner

ID#:531704 **Description:** 1/4 SEC COR 17 20 53 **Date Set:** 4/6/1972 **County:** Olmsted

Section: 17 **Township:** 105N **Range:** 13W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls in old stone quarry 12' east from quarry wall
Post w/sign 1' west
This corner is located by GPS reference stations "Quarry Wall A & B"

Corner History:

11-1853 Gov't Notes William B. Yerby, Deputy Surveyor West on true line between sections 17 and 20. 40.035 chs. Set a quarter section post. Br. Oak 15 in. N80°E 61 lks. Br. Oak 12 in. S62-1/2°E 122 lks.

5-1856 Thomas Hunter (P.4 No.7), County Surveyor, used corner in subdividing Section 17.

11-1883 T. Hunter (P.386 No.377) set corner at the intersection of the lines blazed West and South in earlier days.

1-1900 Robert Fraser (Old Field Bk. 15, P. 21-22), County Surveyor, used a point midway and on line from SW Cor. Sec. 17 to SE Cor. Sec. 17 as the corner.

9-1933 John Kerr (Bk. 9. P.1), County Surveyor, ran line from a corner post taken as the S 1/4 Cor. Sec. 20 over a stone found at the Center of Sec. 20 and found that 1/4 Cor. 17-20 came in a stone quarry.

11-1939 John Kerr (P.542B) records 1/4 cor. 17-20 as an iron bolt in the stone quarry.

4-6-1972 County Surveyor set a CIM over the bolt recorded by Kerr as the corner.

5-6-1976 County Surveyor found the CIM in the old stone quarry and took new references. Spike and CSD in 6" blazed Elm NE 9.25', Spike and CSD in 6" blazed Elm SE 24.83', Spike and CSD in 9" blazed Elm SW 9.45'.

3-1981 County Surveyor set sign & post.

5-20-1982 County Surveyor, 1/16 East: Found 7/8" rod set by Kerr (up 6") and identified Brg. tree, a Hard Maple N 69° 30' W 22.0 Ft set 12-8-1939 (Book 16 Page 59) blazzed tree again and blazed another Maple N'ly 36.6 did not measure in. Kerr pt. 471.0 South of 1/16 E of 1/4 cor. 17-20: Found spike on bank (above drop off) on South side of woods road. Did not measure in.

12-2-2002 County Surveyor found CIM down 0.8' in good condition. Monument falls 12' East from quarry wall.