Certificate of Location of Government Corner

ID#:531705 **Description:** SEC COR 17 18 19 20 53 **Date Set:** 8/4/1964 **County:** Olmsted

Section: 17 **Township:** 105N **Range:** 13W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 1/2' east of N-S fence and 96' south of junction of N-S fence with pasture fence NW
Hub, and Redbrand sign nailed to 24" Elm N20°E 4.2'
30d nail in each side of 12" blazed Burr Oak N 23.35'
Spike in E side 13" Burr Oak N 23.39'
County Survey Disk in SW side blazed 17" Burr Oak NW 38.83'
Post w/sign 1' south
This corner is located by GPS reference stations "Mathy B & C"

Corner History:

1854 Gov't Notes M.G. Karrick 80.00 set post to cor section 17,18,19 and 20. Bur Oak 10 S 75 E 174. Bur Oak 10 W 50 W 707. Dug trench.

11-1939 J. Kerr set 63" long twisted steel rod as corner at spot pointed but Mr. Schully who remembers survey.

12-1939 J. Kerr used corner for line South. Meas South 2621.37 to 1/4 corner an iron shaft.

12-17-1962 J. Kerr found 3/4" steel bar twisted. RPs- 14" elm N21sign post 1' So. of CIM E 5.0', 12" oak N30sign post 1' So. of CIM W 38.9', 24" oak N48sign post 1' So. of CIM W 5.4'.

8-4-1964 J. Kerr found 3/4" by 63" twisted rod 8" above ground, and crockery. RPs- 3/4"x63" twisted steel rod up 38" W 0.5', 30D nail on east side 12" blazed oak in fence line N 23.35', hub & nail thru Red Brand sign nailed to 24" elm trunk which 4' above ground divides into 4 smaller trunks N20°E 4.2', center 6" elm SE 18.35.

7-1979 County Surveyor set sign post 1' So. of CIM Add'n R.P. Spike in County Surveyor Disc in SW side blazed 17" Burr Oak NW 38.83', spike E side 13" burr oak in fence line north N23.39.

3-16-2005 County Surveyor found CIM in good condition down 0.1'. Monument falls 0.5' east of N-S fence. Sign & post 1.0' south but sign fences east. Did not look for ties.