Certificate of Location of Government Corner

ID#:532004 **Description:** 1/4 SEC COR 20 29 53 **Date Set:** 7/25/1979 **County:** Olmsted

Section: 20 **Township:** 105N **Range:** 13W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls under E-W fence and 1/2' east of fence north
County Survey Disk in N side 24" twin Black Oak NW 67.60'
County Survey Disk in NE side 12" twin Burr Oak NNW 11.89'
Post w/sign 1' west
This corner is located by GPS reference stations "McClelland A & B"

Corner History:

5-1854 Gov't Notes Michael Karrick, Deputy Surveyor West on true line between sections 20 and 29, 40.00 chs. Set quarter section post. Black Oak 12 in. S10°W 70 lks. Bur Oak 10 in. N45°W 60 lks.

12-1884 Thomas Hunter, County Surveyor, (Old Field Book 14, Page 29) "found old stake standing by side of stone. Could find no trace or stumps to correspond." At the 1/16th North he set a stake midway (19.81 chs.) and on line to a stake at the Center 20. He marked a Jack Oak as the corner at the 1/64th West midway (9.90 chs.) and on line to the fence corner at the 1/16th West claimed by Mr. Radcliff to be where the corner stake stood.

5-1901 William Fraser, County Surveyor, (Book B, Page 10) found a stone and stake at this corner. Set a stake at the 1/16th North on line and midway (19.82 chs.) to a stone and stake found at the Center 20.

9-1933 John Kerr, County Surveyor, (Kerr Book 9, Page 1) states that this corner is the corner fence post.

11-1939 Kerr (Book B, Page 542) shows a stone boulder at this corner.

12-1939 Kerr (Kerr Book 16, Page 75) "went to the S 1/4 Cor. 20 Cor. Fence post is the corner. Set a bluish grey boulder 12"x7"x5" with mark on top packed in limestone shell. Set on top of bottom of old post." He also found a stone 643.3' West.

3-14-1973 County Surveyor found Kerr's stone by the corner post to the fence North.

4-13-1973 County Surveyor dug here but did not find anything.

7-24-1979 County Surveyor dug again but did not find anything further.

7-25-1979 County Surveyor replaced Kerr's stone with a CIM over a 1/2"x16" iron. Set survey marker and sign post 1.25 west. RPs-spike & CSD in NE side 12" twin burr oak NNW 11.89, spike & csd in north side 24" twin black oak NW 67.60, corner falls ± 6' east of old fence north and directly under newer E-W fence.

12-4-2002 County Surveyor found CIM in good condition at surface. Did not check ties.