Certificate of Location of Government Corner

ID#:532005 **Description:** SEC COR 19 20 29 30 53 **Date Set:** 3/16/2005 **County:** Olmsted

Section: 20 **Township:** 105N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in cultivated field
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes: M. Karrick; 80.0 set post for corner to sections 19-20-29-30. RPs- 7" Burr Oak S 38 W 180, 12" burr oak N 57 e 151, 8" Burr oak N 19 E 411, 12" burr oak S 74, W 91.

9-1857 E.P. Bircher and T. Hunter (old road book, road #68) survey a road running east and west from this corner.

12-1884 T. Hunter (old field book 14 pg. 29) at 1/16th east fence corner claimed as where corner stood.

6-1886 T. Hunter (old field book 14 pg. 62) corner gone.

5-1901 W. Fraser Pg.10B; May not have used corner, but found stone & stake placed as 1/16 corner north which was accepted, used 1/16 corner to lay out road east.

12-1939 J. Kerr Bk.16 Pg.57; 3/4" bridge bolt packed in limestone 18" below surface (Bk. 16 Pg. 75 says 3/4" iron). Took measurements east, west, and north.

7-12-1979 County Surveyor found Kerr's 3/4" iron and reference iron. Measured 270' SSE and dipped a 3/4" iron packed in limestone 1' deep. We tied both these irons into our traverse. We set a 5/8" rod and cap 1' south of the E-W fence as traverse point from which the iron were shot.

10-8-2003 County Surveyor did not find iron. Iron falls in cultivated field.

3-16-2005 County Surveyor found 3/4" iron from angle turned using GPS reference pts down 1.2'. Set 5' telspar w/cast iron cap over 3/4" iron rod down 1.2'. Monument falls in between the easterly and middle silo's to the north.