Certificate of Location of Government Corner

ID#:532006 **Description:** 1/4 SEC COR 19 20 53 **Date Set:** 7/25/1979 **County:** Olmsted

Section: 20 **Township:** 105N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1/2' north of CP to fences east, west & south
Center 12" Ash SE 6.6'
County Survey Disk in E side 19" blazed Red Oak SSW 61.68' (grown over)
County Survey Disk in S side 10" Ash W 33.05'
This corner is located by GPS reference stations "Hamm A & B"

Corner History:

5-1854 Gov't Notes Michael Karrick, Deputy Surveyor North between sections 19 and 20. 40.00 chs. Set quarter section post. White Walnut 8 in. S64°W 35 lks. Ironwood 10 in. S48°E 40 lks.

12-1873 Thomas Hunter, County Surveyor, (Old Field Book 3, Page 65) possibly used this corner for an unrecorded survey in the NW 1/4 Sec. 20.

5-1901 William Fraser, County Surveyor, (Book B, Page 10) found "stone and stake" at the 1/16th South (no measure).

11-1939 John Kerr, County Surveyor, (Book B, P.542) shows a large iron shaft at this corner.

12-1939 J. Kerr (Book B, P.548 and Kerr Book 16, Page 75) "found iron bar in fence and angle iron 10 rods East." Measured 2621.37 North to Sec. Cor. 17-18-19-20 and 2627.5 South to an iron set at Sec. Cor. 19-20-29-30.

9-1941 J. Kerr (Kerr book 25, Page 76) states "corner is now a corner post." He took references and measured 2638.6 East to the Center 20.

8-12-1979 County Surveyor found that the corner post to fences E-W-S checked with Kerr's 1941 references to this corner. Also found the angle iron noted by Kerr as 165' East by Kerr in 1939.

7-25-1979 County Surveyor set a square pipe with a Cast Iron Cap as the corner on line from the E 1/4 Cor. 20 over the angle iron found 10 rods East, and 10 rods West of said angle iron. The corner came on the NW side of the corner post. RPs-Corner is 165' west of Kerr's iron found 165' east and on the line from the E 1/4 20 over the iron, Center 12" Ash SE 6.6, Spike and CS Disc in East side 19" blazed Red Oak SSW 61.68, Spike and CS Disc in South side 10" Ash in fence line West West 33.05.

3-16-2005 County Surveyor found telspar pipe w/CIC in good condition up 0.2'. Monument falls 0.5' north of corner post for fence E-W&S. Tie in Oak grown over, tie in Ash still good. Did not check ties. Sign on corner post.