Certificate of Location of Government Corner

ID#:532204 **Description:** 1/4 SEC COR 22 27 53 **Date Set:** 8/27/1982 **County:** Olmsted

Section: 22 **Township:** 105N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1/2' south of E-W fence and 1/2' east of fence south
Spike in S side PP #38065 ENE 2.49'
Nail in E side end fence post SSW 1.39'
Sign on fence post 1 1/2' SSW
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes M.G. Karrick East Random 22 & 27. 40.00 set temp section post. West on true line between section 22 & 27 10° 21'. 40.00 set 1/4 section post. Bur Oak 10 in N 55 W 11 Dug trench.

2-1896 W. Fraser (P591 No.537) corner lost, no evidence or knowledge of any kind. Drove marked stake M & L 39.91 (2634.06). 1/16 West set stake marked 1/16 corner M & L 19.94 1/2 (1316.37). Used corner to set center 22 an iron and wood stakes.

6-1886 T. Hunter (Old Fieldbook 14 Page 64) used corner to set the 1/16 West a stone midway (20. chs) and on line. He also set the center 22 a stake. He set a property corner 11.14 chs. North and 11.14 chs North of 1/16 West.

7-19-1972 County Surveyor using porportions by W. Fraser. Drove 1/2" x 3' reinf rod as corner. Final measure West 2633.37 (R 2632.74). Final measure East 2634.69 (R 2634.06). Corner comes 1' East of corner post in line main fences. South and West found very old post stub near corner.

8-27-1982 County Surveyor set cast iron cap on telspar pipe .24 South and .09 East of the 1/2" rod (removed) set in 1972. Corner set at the intersection of the line from the N 1/4 cor 22 over the center 22 and the line from the SW corner 22 to the SE corner 22 by e.t.c. The corner .5 South of E-W fence and .5 East of the fence South.

11-16-2009 County Surveyor found cast iron cap on telspar pipe up 0.8' in good condition.