Certificate of Location of Government Corner

ID#:532305 **Description:** SEC COR 22 23 26 27 53 **Date Set:** 7/10/1972 **County:** Olmsted

Section: 23 **Township:** 105N **Range:** 13W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 3' west of centerline of old road used by local landowners as field road
20d nail in hub on S side 16" Cherry E 37.3'
20d nail in NW side 12" Burr Oak SW 35.3'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes M.G. Karrick 80.00 set post in mound with trench, pitts and charred stakes and osage orange seeds at each angle from corner to section 22,23,26,27.

4-1895 W. Fraser Bk. A pg. 563 Corner gone, Dug a rod square and then set a stone in line with the fe. running West and at proportionate meas. From SW 22 to SE of sec. 23. Set 1/16th corner stones North and East.

2-1896 W. Fraser (P591 No.537) found stone (P563). Measure West 39.91 to (2634.06) stake driven M & L. Meas North see P563 which is 1316.04. 1/16 North set stone and stake M & L 19.94 to stone and iron stake set P563 M & L 39.88 (2632.08) also P563 not put down. 1/16 East set stone and stake M & L 19.91 1/2 to stone set M & L 39.83 (2628.8) also 1/16 center SW 1/4 23 stone and stake set inters lines.

7-10-1972 County Surveyor found the recorded stone and the 1/16th stone North. Set a CIM over the original stone with a 1/2" by 15" iron below the stone. RPs-37.3 E to 20D nail in hub on S side of north 16" trunk of clump of cherry tree, 35.3 SW to 20D nail in NW side 12" burr oak.

7-10-1972 County Surveyor at 1/16 corner north found pointed limestone near center of old unused road at 1316.5. Set elec. Fence post centering over stone with piece of old stake found on west side stone found. RPS- 85.0 ESE to 20D nail in hub on S side hugh oak in open field, tree 108" circ. Over 3' dia., 15.08 E to conc nail S side corner fence post. Corner lies 2.5' north of eye line of fence east.

12-22-2003 McGhie & Betts found and used monument in survey of NW 1/4 section 26.

11-16-2009 County Surveyor found CIM down 0.5' in good condition.