# Certificate of Location of Government Corner

**ID#:** 532509 **Description:** SEC CEN 25 53 **Date Set:** 8/1/2007 **County:** Olmsted

**Section:** 25 **Township:** 105N **Range:** 13W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.

1" square pipe w/cap RLS #15809

**Reference Ties:**

The corner falls 7' south of centerline of 105th Street SE west and in centerline of CSAH 19
The monument is at the surface
County Highway Disc in SE side PP #40604 NE 121.43'
Punch hole in S end CMP WSW 37.28'
Punch hole in N end CMP NW 44.93'
This corner is located by GPS measurement

**Corner History:**

9-23-1885 Thomas Hunter, County Surveyor, (Book A, Pages 401-402, Survey No. 391 and Old Fieldbook #14, Pages 49-50) set 5"x6"x20" stone at intersecting quarter lines. 1/16th North set 6"x7"x20" stone midway and on line at 20.05-1/2 chains (1323.63') to North 1/4. 1/16th South set 4"x5"x15" stone midway and on line at 19.95 chains (1316.70') to South 1/4. 1/16th East set stone midway and on line at 19.96 chains (1317.36') to East 1/4. 1/16th West set stake midway and on line at 20.04 chains (1322.64') to West 1/4. 1/16th Center of SW 1/4 set stone at intersecting sixteenth lines. 1/16th Center of SE 1/4 set stone at intersecting sixteenth lines.

6-22-1938 County Highway Department, (C.H.D. Book #96, Page 1) found stake and 5"x6"x20" stone down 1' near west track. There was also a 3/4"x2"x?" long bar near the stone. Set 3/4"x24" iron riser. RPs - Spike in big Willow NW 56.4', Spike in big Willow WNW 102.3', Spike in third fence post west of corner post WSW 72.7'. 1/16th North found 5"x7"x20" stone broken in three pieces. Set nail in stone. 1/16th South found 4"x5"x15" stone at surface.

8-1965 County Highway Department (C.H.D. Book #307, Page 3) found wooden hub with tack over 5"x6"x20" stone.

11-20-1967 County Highway Department (C.H.D. Book #307, Pages 2-3) set Cast Iron Monument. RPs - Disc in tree NW 93.43', Disc in PP NE 121.49', Disc in TP ESE 61.45'. 1/16th North found hub and stone and set Cast Iron Monument. RPs - Disc in fence post E 59.85', Disc in TP NE 95.23', Disc in PP SW 81.2'. 1/16th South found stone and set Cast Iron Monument. RPs - Disc in fence post NE 68.99', Disc in corner post E 60.17', Disc in corner post W 60.12', Disc in PP #13202 NW 63.30'.

6-26-1970 Roger Brand, County Surveyor removed Cast Iron Monument and set 1/2" rod as a temporary corner. RPs - Disc in tree NW 93.43', Disc in PP NE 121.49', Disc in TP ESE 61.45', Punched cross in south end 18" CMP WSW 37.18', Punched cross in north end 18" CMP NW 44.88', Center large steel corner post in concrete NW 79.88'. 1/16th North found Cast Iron Monument, removed and set long, large drill steel rod. RPs - Center 2-1/2" steel corner post W 56.65'. 1/16th South found Cast Iron Monument, removed and set rod. RPs - Punched cross in south end 18" CMP NW 59.87', Punched cross in North end 18" CMP NE 45.48'.

7-20-1982 County Surveyor dug at 1/2" rod set 6-26-1970. Found Hunter's recorded stone down 4' and beneath rod. There was a short 5/8" rod over the stone. Set this rod on the west side of the stone and set the 1/2" rod over stone at the surface.

7-21-1982 County Surveyor 1/16th North dug on east side of rod in place. Found nothing.

8-13-1982 County Surveyor removed the 1/2" rod and set 1" square pipe with cap at surface. The corner falls 7' south of centerline road west and in centerline of CSAH 19. RPs - County Highway Disc in SE side PP #40604 NE 121.41', Punch hole in south end CMP WSW 37.25', Punch hole in north end CMP NW 44.90'. 1/16th North removed drill steel and set rod with cap 1.28' South and 1.24' East to be midway and on line. The corner falls in line with fence east, 1' south of fence west, and 1-1/2' east of centerline of CSAH 19. RPs - County Highway Disc in PP #13212 SW 80.76', Punch cross in north side pipe corner post W 57.91'.

1-13-1987 Jerome Schwarz found and used 1" square pipe w/cap at intersecting quarter lines.

12-10-1999 GGG found and used monument at intersecting quarter lines.

10-7-2004  County Survey Crew found 1" square pipe w/cap up 0.1' in good condition.  Lowered pipe and measured its position using GPS.

4-25-2007  County Survey Crew found 1" square pipe w/cap at surface in good condition.  Referenced prior to bituminous overlay project.

5-25-2007  County Survey Crew removed 1" square pipe w/cap.

8-1-2007  County Survey Crew set 1" square pipe w/cap at previously referenced position at surface. Updated ties.

3-30-2018  Mark Severtson, County Surveyor, recommends using the computed intersection of quarter lines for the center of section. Based on the county's section breakdown, the 1" square pipe w/cap, as located by GPS in 2007, matches the computed intersection of quarter lines.