Certificate of Location of Government Corner

ID#:532705 **Description:** SEC COR 27 28 33 34 53 **Date Set:** 5/31/1978 **County:** Olmsted

Section: 27 **Township:** 105N **Range:** 13W **Monument Description:** Cast Iron Monument

Reference Ties:

Post w/sign 2' south
This corner is located by GPS reference stations "Lo-Mill A & B"

Corner History:

5-1853 Gov't Notes M. Karrick, Deputy Surveyor North between sections 33 and 34. 80.00 chs. Set post in mound with trench, pits and charred stake and Osage orange seeds planted at east angle for corner to sections 27-28-33-34.

8-1902 OH Case Pg.45 B; Copy of survey made sent to W.Fraser. Run line from SE 33 to E 1/4 28. Set 1 1/4"x40" pipe and stone 4x16x16 on north side which came near brace post as claimed by a Mr. Rider owner of N 1/2 of NE 1/4 33. Meas. South 39.80 to 1 1/2"x40" pipe set as 1/4 cor M & L.

8-1920 O.H. Case (Book B P.45), Fillmore County Surveyor, ran line from the SE Cor. 33 to the E 1/4 Cor. 28 and "at the North East corner the owner of that N2 NE4 Mr. Rider says the section corner was at or near a brace post in his fence and I found it to be so from a division of the distance from the SE Cor. to the East quarter-corner of sec. 28." Set a 1-1/4"x40" iron pipe and stone 16"x16"x4" on the North side.

7-1930 County Highway Department (C.H.D. Book 57 P.43) found the pipe and stone as recorded on the East side of the corner post.

1950's TH 30 R/W map shows meas. Of 1883.0' south to centerline T.H. 30 at P.D.T. 292+15. No indication of what was used at this section corner.

4-11-1978 County Surveyor found a 1-1/4"x40" pipe with a 4"x16"x16" stone on the North side as recorded by Case.

5-31-1978 County Surveyor drove Case's pipe down and set a CIM over it.

8-10-1979 County Surveyor dug at double the line and measure from the stake found a 1/4 cor 28-33 over the corner post at the 1/16 East. This point came appx. We found the remaining 2' of a post of appx 7" diameter top down 2' 9.35 West of the CIM. Drove a 5/8" iron down through the center of the post stub and set it back at the location it was found, could not be sure this was not just an old post in the E-W fence line. Dug from the post stub 1' North, 1' East, 2' South and 3' West but found nothing further.

12-19-2002 County Surveyor found CIM up 0.2' in good condition. Set sign & post 2.0' South of monument.