Certificate of Location of Government Corner

ID#:532804 **Description:** 1/4 SEC COR 28 33 53 **Date Set:** 1/11/2006 **County:** Olmsted

Section: 28 **Township:** 105N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 8' west of centerline of CSAH 1 and 4' south of fence east
County Survey Disk in S side CP ENE 58.12'
This corner is located by GPS measurement

Corner History:

5-1854 Gov't Notes Michael Karrick, Deputy Surveyor West on true line between sections 28 and 33. 40.00 chs. Set quarter section post in mound with pits, trench, and charred stake and Osage Orange seeds NE and SW 80.00 chs. To section corner.

1855 Henry L. Edwards, Surveyor, possibly used this corner to establish the N-S 1/4 line of Sec. 28 for the Pleasant Grove plat.

1856 William Mills, Surveyor, possibly used this corner to establish the N-S 1/4 line of Sec. 28 for the survey of Barrow's and Brittendall's Addition to Pleasant Grove.

4-1856 E.P. Bircher, Surveyor, and Thomas Hunter, Deputy, (Old Road Book--CR 8) used this corner in survey of old road.

8-1902 O.H. Case, Fillmore County Surveyor, (Book B, Page 45) measured the north line of Section 33 after setting the NE Cor. 33. He used some point as 1/4 Cor. 28-33 (no description or measurement given) to set the Center 33 and the 1/16th South of the Center 33.

1920 County Highway Department (C.H.D. Book 35) used a point (no description given) which came in line with the fence West, in line with the centerline of the road East, and 5' East of the fence line North.

1930 County Highway Department (C.H.D.) Book 57 Page 11) assumed a point here (no description) as the corner. Also found the S 1/4 Cor. 33 and Case's Center 33.

1956 County Highway Department (C.H.D. Book 218) shows a 3/4" rod in place as a P.I. In CR 1 RPs- hub NW 71.40, hub SW 75.40; Old ties- spike in tele pole NE 53.1, corner fence post east 34.6, 4th post S of corner fence post 54.12 NE?

5-1978 County Surveyor found the S 1/4 Cor. 33 and Case's corner at the 1/16th North. Ran the line north from the S 1/4 Cor. 33 over the 1/16th North and found the 3/4" iron at 1/4 Cor. 28-33 on this line. (Did not dig up the Center 33 which falls in TH 30.)

6-2&7-1978 County Surveyor dug at the 3/4" County Highway Department iron. Did not find anything. Set a 1/2" rod back at the County Highway Department location. RPs- + in lug at top West end 24" C.M.P. SSW 131.95, CSD in south side corner post ENE 51.35, corner in centerline & 2' south of fence east.

7-23-1979 County Surveyor dug again to cover a point at double the line and measure from Sec. Cor. 28-29-32-33 over the fence corner at the 1/16th East. Found a 9" diameter black mark in clay. Dug down in the mark and found the remaining 8" of a stake with the axe marks plain. Set a 1" square by 18" pipe at the stake location.

7-26-1979 County Surveyor set a CIM over a 1/2"x18" rod at the location of the stake found 7-23-1979. Removed 1/2" rod traverse point. The corner is 6 1/2' west centerline and 3' south fence line east. RPs- CSD dics in south side corner post ENE 58.05, punched cross in lug at top west end 24" C.M.P SSW 129.53.

12-27-2002 County Surveyor found CIM down 0.5' in good condition.

6-13-2005 County Surveyor found CIM down 0.5' in good condition. Set 2 points and tied out corner for 2005 overlays.

1-11-2006 County Surveyor set 1" square pipe w/cap at surface from 2005 overlay.

2-23-2009 County Surveyor found 1" square pipe w/busted cap at surface in good condition. Replaced cap.