Certificate of Location of Government Corner

ID#:533004 **Description:** 1/4 SEC COR 30 31 53 **Date Set:** 10/16/1991 **County:** Olmsted

Section: 30 **Township:** 105N **Range:** 13W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 7' south of centerline of E-W twp road, 37' west of centerline of field entrance south and 55 1/2' east of fence north
Punch cross in W side iron pipe standard for satelite dish NNE 40.65'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes M.G. Karrick set 1/4 section post in mound with trench pitts and charred stake and osage orange seeds NE and SW 40 chs. then 39.83 to West 30-31.

6-6-1989 County Surveyor, we set up Gov't proportion location which comes 6' S of centerline we dug from 2' S to 8' North of this spot and also 5' West and 11' East. This also covered doubling a fence ridge at the 1/16th South for E-W location. We dug to clay at 4.5' deep found nothing.

10-16-1991 County Surveyor set CIM over 1/2" iron at prorated position and on line between section corners. The corner falls 7' South of centerline of E-W twp road. RP's punch cross in West side of iron pipe standard for satelite dish NNE 40.65'. Line of farm yard fence running North on West side of farm yard West 55 1/2' E centerline field drive South East 37'.

9-19-2006 County Surveyor found CIM down 0.6' in good condition.

8-18-2009 County Surveyor found CIM down 0.6' in good condition.