Certificate of Location of Government Corner

ID#:533006 **Description:** W 1/4 SEC COR 30 53 **Date Set:** 10/18/2007 **County:** Olmsted

Section: 30 **Township:** 105N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CSAH 20 and 11' south of centerline of E-W twp road
Ref iron W 158.74'
This corner is located by GPS measurement

Corner History:

Gov't Notes 40.00 set quarter section post. Bur Oak 6 S 22° W 55. Bur Oak 6 S 23° E 165.

7-7-1965 J. Kerr found 1/2" steel rod & placed cast iron monument over 1/2" steel rod. RPs- disc in tele pole SW 40.5, disc in pp NW 57.3, disc in pp NE 59.3, corner lies on center of road running north & south, corner lies 3' north of the south edge of roads running E & W.

6-1-1989 County Surveyor set 1/2" iron as RP on line to P.K. nail in face of PP #47502 WNW of CIM at corner.

6-2-1989 County Surveyor dug with backhoe to cover 8 int of RD's N-S-E-W dug from 6' No. of CIM to 16' North and 4' East and West of CIM 6 1/2 deep to clay (found nothing). At 5' deep there was an old road and at 5 1/2' there was another old road on a 2" layer of black dirt all of this was very hard digging. No sign of anything but two boulders in sub soil.

10-17-1991 County Surveyor set 1" square pipe w/cap in new blacktop from transit ties. (See card for ties.) RPs-Corner is 11' south of centerline twp roads running E-W, CSD in PP NE 70.23.

7-20-2000 County Surveyor found 1" square pipe w/cap at surface.

6-11-2002 County Surveyor found 1" square pipe w/cap at surface in good condition.

6-1-2007 County Surveyor found 1" square pipe w/busted cap at surface in good condition. Tied out corner for 2007 overlays.

8-29-2007 County Surveyor removed 1" square pipe w/cap for 2007 overlays.

10-12-2007 County Surveyor set pk nail at surface from 2007 overlay tie out.

10-18-2007 County Surveyor set 1" square pipe w/cap at surface over pk nail.