Certificate of Location of Government Corner

ID#:533204 **Description:** S 1/4 SEC COR 32 53 **Date Set:** 6/23/1981 **County:** Olmsted

Section: 32 **Township:** 105N **Range:** 13W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 2' south of E-W fence and 24' east of fence north
Post w/sign 0.1' north
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes E. Norris, Deputy Surveyor, West on the South boundary of Section 32. 40.00 chs. Set quarter section post. Built mound with trench per instructions. Drove charred stake in center and planted apple tree seed in NW corner.

1853 Gov't Notes Phipps and Fitzpatrick, Deputy Surveyors, North between Sections 4 and 5. 76.75 chs. Intersect N Boundary 208 lks. West of corner and set a stone 12 inches long, 12 inches broad, and 4 thick for corner to Sections 4 and 5.

5-1893 Will Fraser, Deputy County Surveyor, (Book A, No. 493, page 528-529) could not find this corner. He set a 18"x8"5" stone "on line and according to measurement (prorated Gov't measure) between A (SW corner 31 and F (S 1/4 corner 33)." He shows a measure of 2.08 chs. West to the N Sec. corner 4-5.

9-1893 Will Fraser (Book A, No. 494, page 530) set N Sec. corner 4-5, 104-13, 2.08 chains West of this corner as per Gov't Survey and on line between the NW corner twp and the S 1/4 corner 33, 105-13. Planted stone 18"x8"x3".

4-1942 John Kerr, County Surveyor, (Kerr Book 27, P. 4) found "limestone in place 2639.8 East of SW corner. Drove stake by side. R.P. 5" Bro. E. 142.0".

5-1981 Fillmore County Surveyor dug at a point midway and on line between the section corners. Found pieces of a shattered limestone. The lost position came .05 North and .14 East of the center of the shattered stone.

6-23-1981 Fillmore County Surveyor set a Cast Iron Monument (down 1.2) marked "Surveyor Marker" midway (2640.23) and on line between the SW corner Sec. 32 and the SE corner Sec. 32. He set a survey marker sign and post .9 North of the CIM. The corner is 2' south of E-W wire fence and 24' East of the old corner post to the fence north.

8-17-2009 Olmsted County Surveyor found CIM down 1.0' in good condition.