Certificate of Location of Government Corner

ID#:533304 **Description:** S 1/4 SEC COR 33 53 **Date Set:** 5/30/1978 **County:** Olmsted

Section: 33 **Township:** 105N **Range:** 13W **Monument Description:** 8"x 8" topped concrete monument

Reference Ties:

The monument is down 1.6'
The corner falls 88' east of centerline CSAH 1.
Spike in S side PP NW 41.73'
Spike in W side PP (up 4') SSW 224.3'
This corner is located by GPS measurement

Corner History:

9-1853 Gov't Notes E. Norris, Deputy Surveyor West on the south boundary of section 33. 40.00 chs. Set quarter section post. Made mound with trench and drove charred stake in center and planted apple seed in NW corner.

9-1893 William Fraser, County Surveyor, (Book A P.528 No.493) set a 4"x6"x25" stone 2 rods West of the corner fence post avered by a Mr. S. Smith to have been set 2 rods East of the corner when standing. The corner came in the center of the road.

8-1902 O. H. Case, Fillmore County Surveyor, (Book B P.45) found the stone set by Fraser.

7-1930 Olmsted County Highway Department (C.H.D. Book 118 p.43) found the stone as described.

1953 Olmsted County Highway Department (C.H.D. Book 201 P.2 and also Certificate filed) found a 4"x6"x25" stone. Set an 8"x8"x30" concrete marker 18" below cultivated field. RPs- corner lines with fence west on twp & county line, 96.0' east of centerline road in 1953, fence post NE 59.8, fence post SE 52.75, spike in PP NE 30.5, spike in fence post SE 29.2, hub east 38.9, hub NE 59.8, hub SE 52.75.

1970's McGhie and Betts found the concrete monument. RPs- spike in pp WNW 41.73, spike in PP SSW 22.43, monument is 90' east of centerline CR 1.

5-30-1978 Olmsted County Surveyor found an 8"x8" topped concrete monument down 16" in cultivated field. Set 1/2" rods on the North and South sides of the monument and took references. RPs- spike in south side PP NW 41.73, spike in west side of PP SSW 224.3.

4-1984 Vince Fangman found 8x8 conc. Monument at S 1/4 33. 1/16 north; Set 3/4" pipe M & L to pipe set at center 33. This survey came .06 west and .45 north of C.S. point untied. RPs- pop can in 2nd fence post east E 57.34, pop can in NE side pp SE 58.56, and set 3/4" pipes 445.0 north and 762.0 north of S 1/4 33.

11-14-1984 Olmsted County Surveyor found concrete monument in plowed field O.K. but disc now gone. Chiseled mark where stem of disc is still in the concrete.

10-28-2010 Olmsted County survey crew found concrete monument in good condition.