Certificate of Location of Government Corner

ID#:533405 **Description:** S SEC COR 33 34 53 **Date Set:** 6/2/1978 **County:** Olmsted

Section: 34 **Township:** 105N **Range:** 13W **Monument Description:** Cast Iron Monument

Reference Ties:

The monument is at the surface
The corner falls 157' east of the line of the fence south
Post w/sign 1/2' east
This corner is located by GPS measurement

Corner History:

9-1853 Gov't Notes E. Norris, Deputy Surveyor West on south boundary of section 34. 80.00 chs. Set post for corner to sections 33 and 34. Made mound with trench and drove charred stake in center and planted apple seed in NW corner.

9-1893 William Fraser, County Surveyor, (Book A P.528 No.493) measured from the SW Cor. Sec. 31 to the SE Cor. Sec. 36 overrunning 15 links. He dug and plowed for every 1/2 mile corner and found nothing. He set the S 1/4 Cor. 33 at the location avered by a Mr. S. Smith which also agreed with the prorated location. He then set each 1/2 mile corner West of the S 1/4 Cor. 33 on line and at the prorated location (40.01-1/4 chs.). He does not, however, show that he set the corners East of the S1/4 Cor. 33.

8-1902 O.H. Case, Fillmore County Surveyor, (Book B P.45) set a piece of cast iron as the corner and shows it 40.01-1/2 chs. East of the S 1/4 cor. 33 which he found.

7-1930 Olmsted County Highway Department (C.H.D. Book 51 P.43) found the cast iron piece recorded by Case.

6-2-1978 Olmsted County Surveyor found a 1"x2" topped piece of iron down 1/2', 1/2' South of the E-W fence. Drove the iron down and set a CIM over it. The corner is 157' east of the line of the fence south.

11-14-1984 Olmsted County Surveyor N 1/4 cor. 3 Sumner Twp: Found 1 1/2" x 2 1/2" topped case iron appx 1 1/2' NW of corner post (leaning SE) to fences East and South but in line with fences East and South from down 1/2' but in danger of being plowed out. 1/16 East of N 1/4 cor. 3 Sumner: Dug around corner post, but post set in large piece of concrete which could have been a corner now disturbed when concrete post set. Fence line here appx 2' farther South than corner post at 1/16 East of S 33-34 which is East.

11-4-2010 Olmsted County survey crew found CIM in good condition