Certificate of Location of Government Corner

ID#: 533406 **Description:** 1/4 SEC COR 33 34 53 **Date Set:** 11/3/2010 **County:** Olmsted

Section: 34 **Township:** 105N **Range:** 13W **Monument Description:** Cast Iron Cap on Telspar Pipe

Reference Ties:

The monument is down 0.4'
The corner falls 2' north of centerline of E-W twp road, 6 1/2' east of fence north and 3 1/2' east of fence south
County highway disk in PP N 30.8'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes M.G. Karrick 40.00 set 1/4 section post in mound with trench, pitts, charred stake and planted osage orange seeds NE and SW of trench.

8-28-1902 O.H. Case (Page 45 Book B) Copy of survey made sent to W. Fraser. Set 1 1/2" x 40" iron pipe midway and on line between section corners.

7-23-1930 County Highway Department (Book 57, Page 44) found iron pipe

8-4-1964 J. Kerr placed CIM over 1 1/4' recorded pipe down 1'. Established 6 reference or witness monuments consisting of fence lines, 3 disc. and centerline of road. RPs- disc in treated brace fence post SSW 31.5, disc in pp N 30.8, disc in tele pole ESE 88.7(gone), corner 3.7' east of fence north and lies 3.7' east of fence running south, corner lies 2.0' north centerline traveled road E-W.

6-2-1978 County Surveyor, 1/16th South Dug 3' x 3' on the Southeast side of the traverse nail by the corner post but found nothing.

11-3-2010 Olmsted County survey crew found CIM down 1.3' with top broken off in good condition. Removed and found a 1 1/4" x 3' pipe directly below, down 2.9' in good condition. Removed and replaced with a 6' telspar pipe with cast iron cap.