Certificate of Location of Government Corner

ID#: 533605 **Description:** S SEC COR 35 36 53 **Date Set:** 11/2/2010 **County:** Olmsted

Section: 36 **Township:** 105N **Range:** 13W **Monument Description:** Cast Iron Cap on Telspar Pipe

Reference Ties:

The monument is down 0.5'
The corner falls 5.5' north of centerline of E-W twp road and 2' west of centerline of twp road north
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes Elisha S. Norris, Deputy Surveyor, West on South boundary of Sec. 36. 80.00 chs. Set post for corner to Sections 35 and 36. Built mound with trench per instruction. Drove charred stake in center and planted Apple tree seed in NW corner. We could find no other survey records of this corner.

5-29-1981 Olmsted County Surveyor dug for this corner but did not find it.

9-9-1982 Olmsted County Surveyor set a Cast Iron monument over a 3/4"x15" iron as the corner. We set this corner E-W midway (2641.32) between the S 1/4 Cor. 35 (stake found--See Cert.) and the S 1/4 Cor. 36 (set this survey on Gov't tie to the NE Cor. 1, T104N, R13W, found 1981). We set the corner N-S on the line from the S 1/4 Cor. 35 over the stone found at the N 1/4 Cor. 1, thus accepting and preserving the stone found at the N 1/4 Cor. 1 as having been properly set although we do not have a record of the survey. RPs- punchhole in top west end CMP NW 30.48, punch hole in top east end CMP NE 32.28.

8-11-2004 Yaggy Colby Survey Crew found monument in good condition down 0.5'.

11-2-2010 Olmsted County survey crew found CIM with head broken. Removed and found 3/4" rod directly below, down 2.3'. Removed and replaced with a 5' telspar pipe with Cast Iron Cap down 0.5'