Certificate of Location of Government Corner

ID#: 540105 **Description:** SEC COR 1 2 11 12 54 **Date Set:** 11/20/2003 **County:** Olmsted

Section: 01 **Township:** 105N **Range:** 14W **Monument Description:** Cast Iron Cap on telespar pipe

Reference Ties:

The corner falls 4' west of centerline of N-S twp road and 1' north of fence east
County Survey Disk in PP #47330 E 39.01'
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes W.B. Yerby, Deputy Surveyor North between sections 11 and 12. 80.00 chs. Set post corner to section 1,2,11, and 12. Burr Oak 12 in. N82°W 446 lks. Aspen 12 in. S2 1/2°E 391 lks. Made trench.

2-1872 Thomas Hunter, County Surveyor, (P. 193 No. 204) states that the corner was gone. He reset the corner from the stump of a Burr Oak which a Mr. William Freeman avered to be an original Gov't bearing tree.

5-1876 Thomas Hunter (P. 294 No. 289) used this corner to measure the line North.

11-1907 Charles Armstrong, County Surveyor, (P. 110B) states that the corner was gone. Dug 4' deep by 20' square. He set a blue granite boulder 20" x 16" x16" "on proportionate measure according to record" between Section Cor. 11-12-13-14 and 1/4 Cor. 1-2 and E. Sec. Cor. 1-12 and Sec. Cor. 2-3-10-11. The corner came in the West wheel track of the road and in line with the fence East. He set a limestone 1 1/2" x 18" x 26" midway and on line at the 1/16th North.

9-1924 County Highway Department Book #43 Shows corner.

1962 County Highway Department Book #268 Page 31 1/16 Corner west 1-1/2" pipe. county highway department found 7/8" steel over boulder. RPs- spike & disc in pp E 38.42', spike & disc in TP SSW 45.95', T mark in west headwall culv. South 98.02'.

7-1965 John Kerr, County Surveyor, found an iron rod riser over a stone. Set a CIM over the rod. RPs- spike in pp E38.7, 120D north side cottonwood W73.86, spike in telephone pole SW 46.03, cross in headwall west end culv north end SSW 97.98, corner lies 6' from west edge traveled new grade, corner lies 1' north fence running east.

9-9-1971 County Surveyor found Kerr's CIM down 30". Set another CIM over the CIM in place.

5-17-1977 County Surveyor dug with backhoe along the East side of the CIM. Found the CIM over another CIM over an iron over a blue-green boulder 6' deep. Found Armstrong's recorded stone at the 1/16th North very near midway and on line.

9-1989 County Surveyor found CIM with broken head.

11-20-2003 County Surveyor found CIM down 0.5' with head broken off. Removed CIM and found another CIM down 2.7'. Removed CIM and found 3/4" iron rod down 5.1'. Set 5' telspar pipe w/CIC over iron rod down 0.6'