Certificate of Location of Government Corner

ID#: 540205 **Description:** SEC COR 2 3 10 11 54 **Date Set:** 4/6/2004 **County:** Olmsted

Section: 02 **Township:** 105N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The monument is down 0.1'
The corner falls 2 1/2' west of centerline of N-S twp road and 50' north of centerline of water tower driveway west
County Survey Disk in east pole of double PP W 22.13'
County highway disk in cut-off PP SW 37.33'
This corner is located by GPS reference stations "Denaro A & B"

Corner History:

1853 Gov't Notes Yerby 80.00 set post for corner to Sects. 2-3-10-11. Burr Oak 8" N 30 W 172 lks Burr Oak 12 in. N 57 E 361 lks.

6-1876 T. Hunter P. 299 No. 294 corner stake now missing, but corner post of division fence. Running north between John Lemaugh & John McElgun was set by side of stake in mound. Seen few years past by Hunter. 16 west set stake marked M & L 19.76 (1304.16')

11-1887 T. Hunter P. 423 No. 412 found corner post still in mound P.299. 16 east set marked stake direct aerial line M & L 20.16 B north N 3/4°E east N89°40'W.

11-1907 Ch. Armstrong P.110B found stub recorded post set stone LS 4x12x18 came 43-1/2 lks east of corner. J. Linaughs fence. Meas. north 39.84 south 39.89. 16 east set stake M & L 20.16.

11-27-1963 J. Kerr found 1" pipe over limestone after extensive digging. Corner lay in center road before regrading - now lies 1' west of west edge traveled road. Lies 1' south fence running west. Disc in power pole. SW 37.35 Drill steel driven just south of fence running west well above ground W 43.6. 16 east set 1/2x3' rod M & L 1329' see Center 2. 16 north set 1/2" rod M & L. 1315.9 Rec P 110B 1317.3 R. Pabone 1/16 lies 3' east of W edge traveled road. Lies 27.5' east of N-S fence west road RW. Disc PP #8986 SW 105.5.

4-23-1976 County Surveyor, (1/16W) dug 4'x4'x3' deep. Found post hole or stake hole running down 1'± 3.6S and 3.7E of Kastler's rod set on line and 1/4 distance. Hole location 1'W of Hunter's measure from 2-3-10-11 and near computed distance S of straight line between section corner as per Old Survey Book #4 P.132. Accepted as Hunter 1/16th. Set only old fence post in hole as McGhie's will set their corner here. Corner 14' E of N-S fence and 1'S of fence E and in line with row of large trees on E side of fence S.

11-20-1980 County Surveyor took references to CIM before new road grading. Set 5/8" rod 88.00' West (1.3' S. of fence) and on line to another 5/8" rod 166.95 West of CIM (this 5/8" rod is 1.6' S. of fence). Corner before road grading lies 9' West. West of centerline N-S road. The County Highway Department set some hubs east and SE'ly of the corner.

9-18-1989 County Surveyor, CIM top broken off, Ref. rod 88.0' W missing, other ties good.

1-21-2004 County Surveyor could not find. Assumed destroyed by water tower construction.

4-6-2004 County Surveyor set 1" square pipe w/cap down 0.1' from traverse data and property pins.

8-23-2011 County survey crew found 1" square pipe with cap in good condition.