Certificate of Location of Government Corner

ID#: 540206 **Description:** 1/4 SEC COR 2 3 54 **Date Set:** 4/6/2004 **County:** Olmsted

Section: 02 **Township:** 105N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 6' west of centerline of N-S twp road, 2' north of fence east and 1/2' north of fence west
Plastic disc in NE side PP #9754 SE 41.21'
Plastic disc in NE side PP #24963 NW 35.64'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes Yerby 40.00 set temp 1/4 Sect. post South between sects. 2 & 3 39.62 set 1/4 sect post in mound of earth & sod deposited charcoal made trench, pitts, planted Osage Orange seeds E & W.

2-1872 P.193 - 2-1876 P. 294 found stake in mound meas. north 39.52 (2608.32) south 39.92 (2634.62) same meas both - both used to set center sec. east.

6-1876 T. Hunter P299 No. 294 found stake in mound & pits undisputed (no road then) 16 west set marked stake M & L 19.81 (1307.46' to center of 3 a stake set true intersecting lines.

11-1887 T. Hunter P. 423 No. 412 found remains of stake in mound. P. 193 16 east stake, prop corner, M & L 20.08, meas. south 39.84 accepted corner.

7-24-1903 Robert Fraser (page 712, No. 625-1/2) found stone Mr. Higgin had put in place of stone, which he laid flat, measure fit Hunters chained east 20.08 set stake M & L 20.08 to center of section, corner post which Mr. Fulton said he put in place of stake, which was broke off when cutting down a tree.

11-1907 Chas. Armstrong P 110 B found rotted stake with flat unrecorded 7-1903 Book 10 P. 16. limestone on top set 2x3x10 LS on S side renewed stake. Run line from NW 2 over above W 1/4 2 and came to the west of SW2 which makes W 1/4 2 35 lks (23.10) west of direct line between section corners. Meas. north 39.37 (2598.42') south 39.84 (2629.44) to north-south road now. Corner found & used with pipe riser after road established.

9-15-1964 J. Kerr found 1 1/4" pipe over a limestone. Set CIM over pipe. Disc PP ESE 41.0 - square alum disc top cor post E 34.05 punched cross in N end metal culv. sub station SSW 91.2 corner lies at least 3' west centerline road. 2' north fence east. Meas. north 2598.1 with rod on line on hill crest just off west edge road opposite big power pole 1580 S of NW2. See Center 2 & SW 2 for 1/16 E & S.

11-25-1986 County Surveyor found CIM (but top part gone) down 0.5' 5 1/2' West of centerline 2' North of line of fence East, and 1/2' North of line of fence West. RP's: Plastic disc (driven over old disc) in NE side PP #9754 SE 41.28. Square disc in top of corner post ESE 34.54. Plastic disc in NE side PP #24963 NW 35.63.

10-6-2000 County Surveyor found a pipe bent and lying flat down 0.7'. Hole in blacktop for pipe missed ties by 0.40 + 1/-.

4-2-2003 County Surveyor found 5/8" pipe bent and leaning down 0.7'. Removed pipe and found bottom section of CIM down 2' leaning. Removed CIM and found 1 1/4" pipe down 3' in good condition. Set 1" square pipe w/cap down 0.1' over 1 1/4" pipe.

2-18-2004 County Surveyor found 1" square pipe w/cap at surface in good condition.

4-6-2004 County Surveyor removed 1" square pipe w/cap set in 2003. Set 1" square pipe w/cap at surface from traverse data and plat corner data.