Certificate of Location of Government Corner

ID#: 540306 **Description:** 1/4 SEC COR 3 4 54 **Date Set:** 12/22/1986 **County:** Olmsted

Section: 03 **Township:** 105N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1 1/2' north of east-west fence and 1 1/2' east of fence north
This corner is located by GPS reference stations "Oak Summit 6 A & B"

Corner History:

Gov't Notes Yerby 1853 40.00 set temp 1/4 sect. post South 13' on true line between sects 3 & 4. 40.35 Set a 1/4 Sec. post in mound of trench, pits & sod, deposited charcoal. Planted Osage Orange seeds E & W.

6-1876 T. Hunter P.299 No.294 found stake with mound and pits plain, undisputed. Meas. south 39.86 to corner set this survey.

10-1911 Ch. Larson P.162B boulder as 1/4 corner. Meas. north 40.30 to boulder as sec. cor. Meas. south 39.86 to stone found small limestone replaced with boulder 12x16x30. Agreed with Hunters survey Page 299.

1961 McGhie & Betts found boulder stone 1.5' south of corner fence post. Meas. North 2650.9.

12-9-1986 County Surveyor found 10"x10"x5" thick boulder, blackmark beneath stone going down 2'± to a point

12-22-1986 County Surveyor accepted location of boulder & mark as corner see (1986 remon. book) . Set cast iron cap on telspar pipe. Corner 1-1/2' north of east-west fence and 1-1/2' east of fence north.

7-20-2004 County Surveyor found cast iron cap on telspar pipe up 0.4' in good condition.