Certificate of Location of Government Corner

ID#: 540404 **Description:** 1/4 SEC COR 4 9 54 **Date Set:** 5/18/2006 **County:** Olmsted

Section: 04 **Township:** 105N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 126 1/2' NNE of "Restricted Area, Keep Out" sign on fence
Top of NW corner of green electrical box NW 116.45'
Post w/sign 2' south
This corner is located by GPS reference stations "CR 16 E & F"

Corner History:

1853 Gov't Notes Yerby 40.00 set temp 1/4 sect. post West on true line between sects. 4 & 9 V9°15'E 40.00 set a 1/4 sect. post Burr Oak 10 in N63 E200 lks. Burr Oak 12 in S65 E160 lks.

5-1879 T. Hunter P. 358 No. 349 found stone averred by owners of adjacent lands to be where original corner stood. - 16 east set stake M & L 19.89 1312.74 - 2625.48

5-1896 T. Hunter P. 601 No. 546 found stone P.358 set boulder 6 x 9 x 24 in its place. - 16 east set boulder 6x10x12 M & L 19.88-1/2
- 16 west set boulder 7x7x16 M & L 20.03
- 16 south set boulder 12x15x26 M & L 20.00

10-1911 Ch. Larson P. 162B found boulder.

3-1957 McGhie 1" pipe as corner - 5/8" rod 33' N - 46.5' E of cor - Sp guy pole stub SE 38.1 Meas. east 2624.7 (R 2625.5), meas. west 2643.9 (R 2643.1), meas. south 2639.0 (R 2640.0)

1961 J. Kerr set 1-1/4" pipe. RPs-Sp pp SW 6327, Sp pp NW 47.90,

4-25-1972 County Surveyor found pipe at surface of blacktop. Meas. west 2641.39 - Meas south to Center 9 (CIM 2639.49 angle at corner south to west 90°01'09"

1982 County Surveyor found and shot pipe at surface of blacktop. See Drwg. 5 - 17.

1-21-2004 County Surveyor found 1 1/2" pipe w/top mangled with a 60d spike set in the center of pipe down 0.4'. Set 2 points to GPS and replace corner after road regrade.

5-18-2006 County Surveyor set 5' telspar w/CIC down 0.1' from coordinates taken from original corner tie-out. Monument falls 126 1/2' NNE of "Restricted Area, Keep Out" sign on fence, top of NW corner of green electrical box NW 116.45'. Set sign and post 2' south.