Certificate of Location of Government Corner

ID#: 540604 **Description:** 1/4 SEC COR 6 7 54 **Date Set:** 11/2/1982 **County:** Olmsted

Section: 06 **Township:** 105N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is up 0.1'
The corner falls on south side of corner post for fences N-S-E-W
Post w/sign 1/2' west
This corner is located by GPS reference stations "Gordy A & B"

Corner History:

10-1853 Gov't Notes William B. Yerby, Deputy Surveyor Course North 89°56' East on true line between Sections 6 and 7. 39.46 chs. Set a quarter section post. Br. Oak 10 in. N40°E 66 lks. Br. Oak 12 in. S61°E 69 lks. 79.46 chs. To section corner.

4-1872 Thomas Hunter, County Surveyor, (Book A, Page 194, No. 205, and Old Fieldbook 1, Pages 5-6) "Found small stake not marked standing, witness trees cut but stumps standing with marks plain. Tested stake by U.S. Field notes and found correct, set and marked a new 1/4 post and took new witness trees to it as follows--Br. 0.8 in. diam. N37°W 29 lks. & B.O. 15 in. diam. S32°W 115 lks." He used the corner to set the 1/16 East, a stake (with B.T.'s), midway (19.88 chs.) and on line to the NE Cor. 7, and to set the 1/16 West, a stake (with B.T.'s), on line and at prorated Gov't measure (19.87 chs. Then 19.34 chs to the NW Cor. 7) to the NW Cor. Sec. 7. He also set a stake on the line from the 1/16 South of the NW Cor. 7 to the 1/16 South of the NE Cor. 7 and 19.71 chs. S'ly of 1/4 Cor. 6-7.

5-1980 Tom Ferguson (Card) set a pipe at this corner on line between the section corners and at prorated Gov't measure. He used the corner to set the 1/16 East which fell near a fence corner. He also set the 1/16 North, a long spike near creek bottom, and the Center 6, a pipe.

11-1-1982 County Surveyor dug at the 1/16 West and fount a definite mark from the old stake.

11-2-1982 County Surveyor dug at the 1/16 South but could not find Hunter's stake. Found Ferguson's pipe at 1/4 Cor. 6-7 4' North of the fence running East and 1' + East of the N-S fence. Dug but could not find the old stake. Set a square pipe (telspar) with a Cast Iron Cap as the corner on the line from the W Sec. Cor. 6-7 over the stake mark found at the 1/16 East and at Hunter's prorated measure between W Sec. 6-7 and Sec. Cor. 5-6-7-8. (We did not prorate Hunter's distance over the stake found at the 1/16 West since this would have place the corner 2.4 farther East or 3.6 East of the N-S fence and we wanted to stay as close to the fence as possible.) The corner came 3.8 South of Ferguson's pipe (found to be on the line between the section corners) and under the fence running East. This location South of the line between the section corners is also indicated by Hunter's measurements North from his line from the 1/16 South of the NW Cor. 7 to the 1/16 South of the NE Cor. 7. (appx 5 1/2 lks. Kink South). Measured South 1301 1/2 to the E-W fence at the 1/16 South. Measured East 2623.86 to Sec. Cor. 5-6-7-8 and West 2587.56 to W Sec. Cor. 6-7. Could not identify any trees present as Hunter's bearing trees.

7-26-2001 V. Fangman found and used monument in survey of NE 1/4 section 7.

3-21-2006 County survey crew found cast iron cap on telspar pipe up 0.3' in good condition.

11-20-2012 County survey crew found cast iron cap on telspar pipe in good condition.