Certificate of Location of Government Corner

ID#: 540704 **Description:** 1/4 SEC COR 7 18 54 **Date Set:** 8/9/2000 **County:** Olmsted

Section: 07 **Township:** 105N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 11' north of cenerline of E-W twp road and 121' west of centerline of driveway south
County Survey Disk in NE corner pole shed SSE 77.03'
County Survey Disk in NW corner pole shed SW 106.33'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes Yerby 40.00 set temp 1/4 sect. Post W 89°34'E on true line between sects. 7 & 18 39.70 set 1/4 sect. Post. Black Oak 10 in N 5 E 24 lks. Bur Oak 8 in. S 5' E 53 lks.

4-1872 T. Hunter P. 194 No. 205. Corner missing - B trees gone. Established 1/4 post on section line and 40 chs. From SE cor of 7 as Mr. Sullivan avers he helped carry chain when stake was standing and it was 40 chs. - 16 west meas. Carefully stake set above as 1/4 cor. 39.25 Gov't record 39.70 short 45 lks Set marked stake at 19.77 west then 19.48 to Sec. Cor. This shortage of 45 lks. Should legally have been divided up in the entire mile; but Hunter likely prevailed upon by Sullivan to set 1/4 corner at 40 chs. -16 Center SW 1/4 7 set stake inters lines.

5-1874 T. Hunter P. 245 No. 246. Corner missing. Found 1/16 stake west set P. 194. Meas. East 19.77 chs. And set temp point for line south.

10-29-1982 County Surveyor at 1/16 west: Dug with backhoe centered over a point 24' East and 9' North of our t.n. set in center of road and in line with fence North, North 2', south 2-1/2', East 3-1/2, West 4'+. Fill to clay 6' deep. Found nothing. Point came on N edge road.

11-1-1982 County Surveyor at center SE 1/4: Dug from CP to fence E-W-N (CP center 1.3 North of t.n.) North 3', West 3', and East 2-1/2 by 4' deep to clay (black dirt down 3'). Found wood fragments standing vertical in black dirt that may be the remains of Hunter's stake but it did not reach to clay. The remains of a small post stood 1.0 East of this. It did not reach to clay either. Possible stake remains 1.8 North and 1.5 East of the t.n. Stake: t.n. SW 2.4, Spike SE 2.25.

11-1-1982 County Surveyor at center SW 1/4: Dug from the corner post North 5', East 2-1/2', West 2', by 1-1/2' deep to clay. Found nothing but gopher holes. The corner post is 1.0 East of the t.n.

11-3-1982 County Surveyor at center SW 1/4: Dug 2'+ off the West side of the hole dug 11-1-82 to corner line to corner line from the 1/16 East of W6-7 (Fd) over the stake fd. At the Center NW 1/4 (1970). There is another ridge on the West side of the fence in place that would fit this line well. We did not find anything - not even a post mark.

11-3-1982 County Surveyor dug with the backhoe centered over a point 14' North and 16' East of the t.n. (set in centerline road and in line with the fence North) dug for 4' West, 4' East, 4' South and 4' North by 5' deep to clay. Found nothing. Conditions poor. Had to dig over the edge of the road and hole irreg shaped. We were digging on the line from a point 10' North of West 7-18 to 6' North of Sec. Cor. 7-8-17-18 and to cover Hunter's distances from the line projected from the stake mark found at the 1/16 East of W 6-7 over the stake (stone?) found at the Center of the NW 1/4 7 in 1970 as per TH Survey No. 205 and Hunters distance from the line projected from the Calc. Location of the 1/16 E of 1/4 Cor. 6 - 7over the center SE 1/4 Sec. 7 (poss. Stake fd) also per Hunter's Survey No. 205.

11-16-1982 County Surveyor set a 3/4" x 21" re-rod here as a temporary corner since the hole dug here will yet settle. RP's to 3/4" rerod: CSD @ NE Cor. Pole shed SSE 76.94, CSD @ NW Cor. Pole shed SW 106.25. We set this corner independent of the section corners East and West as we believe neither is a perpetuation of the original corner. We calc. The location of the 1/16 West and the 1/16 East where we believe Hunter 's corner stood in Survey No. 205. We then set 1/4 Cor. 7-18 on the line between these 1/16ths and at prorated Hunter measure between them as per Survey No. 205. The corner is 17' East of the fence line North and 12' North of the centerline of the E-W road. Locals to 3/4" rod: t.n. in centerline road and line fe N. SW 20.86, 1/2" re-rod in centerline road. SE 18.52 . We calc the location of the 1/16 W on the line from the stake mark found at the 1/16 E of W 6-7 over the stone Fd at the center NW 1/4 (1971) and at Hunters prorated distance (Prorated against measure from 1/16 E of W 6-7 to Center NW 1/4 8).

We calc the location of the 1/16 E on the line from the 1/16 E of 1/4 Cor. 6-7 (calc only) over the stake fd at the Center SE 1/4 7 and at prorated Hunter measure from Center SE 1/4 7 (prorated against measure from 1/16 E of 1/4 Cor. 6-7 to the Center SE 1/4).

8-9-2000 County Surveyor found 3/8" rod. Removed. Found 3/4" rerod down 1.1'. Set 4' long telspar pipe w/CIC down 0.6' over 3/4" rerod.

10-15-2007 County Surveyor found cast iron cap on telspar pipe down 0.7' in good condition.