Certificate of Location of Government Corner

ID#: 540705 **Description:** W SEC COR 7 18 54 **Date Set:** 4/22/1974 **County:** Olmsted

Section: 07 **Township:** 105N **Range:** 14W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 15' east of centerline of N-S twp road and in centerline of E-W twp road
Nail in PP #7172 NW 68.97'
Nail in PP #7173 SW 72.84'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes: John Ball, Deputy Surveyor North between sections 13 and 18. 80.00 chs. Set corner post and dug trench. Br. Oak 10 in. N3°E 850 lks. Br. Oak 12 in. S5°E 46 lks.

4-1872 Tom Hunter (P.194 No.205), County Survyeor, found stake in center of road and tested bearing tree stumps.

9-1913 D. Williams (P.228 Book B), County Surveyor, could not find corner. Ran the line from NE Cor. Sec. 12 to SE Cor. Sec. 13. Set a 1/2"x2' rod on the township line at 1/2 distance (5268) and on direct line.

10-3-1973 County Surveyor dug and found D. Williams iron but could not find T. Hunter's stake.

4-22-1974 County Surveyor set a CIM over a 1/2" rod which is D. William's corner.

11-4-1982 County Surveyor dug with backhoe from a point 9' West and 6-1/2' North of the CIM in place, West 4', East 4', and North 8' by 4-1/2' deep to clay. Old road right on clean clay. Found nothing. Diggings to corner Hunter's measure from W 6-7 and Hunters measure from the 1/16 East (set up on a projection of the line from the 1/16 East of W-6-7 (Fd) over the stake (stone?) Fd @ the center NW 1/4 Sec. 7 (Fd 1970).

11-4-1982 County Surveyor at 1/16th North dug from a point 1' West of a point set up at Hunter's measure from W 6-7 and on line from the CIM at W 1/4 Cor 7 to CIM @ W 7-18 West for 6'. Found nothing. Slight road cut here. Not good condition. Digging assuming the W 1/4 Cor. 7 fairly close E-W and assuming Hunter's W 7-18 was near location we dug at there 11-4-82.

The work in the interior of Sec. 7 used to reset 1/4 Cor. 7 - 18 says Hunter corner here should be appx. 11' N and 10' West. Measure North says 10' North. The line from the S 1/4 Cor 18 over the post found at the Center 18 says 17-1/2' West which agrees with Hunter's call for the center of the road. Then SE Cor. 7 goes 15-1/2' West which would agree with Hunter's kink at 1/4 Cor. 7 -8.

7-28-2000 County Surveyor found CIM in good condition.