Certificate of Location of Government Corner

ID#: 540706 **Description:** W 1/4 SEC COR 7 54 **Date Set:** 6/25/2007 **County:** Olmsted

Section: 07 **Township:** 105N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 10 1/2' east of centerline of N-S twp road, 49' south of centerline of residential driveway west and in line with fence west
County Survey Disk in PP #42680 NW 114.2'
This corner is located by GPS measurement

Corner History:

4-1872 T. Hunter P. 194 No. 205 found stake standing in grove, tested B trees, found correct - 16 N. set stake M & L 1990 N 1°10'E (1313.4 (2626.8) - Meas. south 39.66 (2617.56 N 52" E. Corner not midway not on line, 16 N lies 19.35 west of 1/16 E which is center NW 1/4 7 (1277.1 then 19.77 (1304.82 to 1/16 stake on N-S 1/4 line.

9-1913 D. Williams P. 228 B found limestone at NW 7 - ran & meas. 2 miles south to boulder stone in road at W 18-19. - Set 1/4 post as corner with 2 witness trees. 8" B. Oak. NE 37.5 - 9" B. Oak SE B 1.0' - each 1/2 mile 26.34' - corner in east road ditch, 10' north of fence west.

Corner in long controversy as line and meas varies. example R Hunter 4-1872 P. 194 5244.36 Dave Williams 9-1913 P. 228 B 5268.0 final D. Williams iron to CIM W 6-7 5254.51 11-5-73. Hunter gave no hint as to directness of line and comp. meas. indicates some kink but using Williams corner direct line as W 1/4 7 comes near recorded meas. east N 1/2.

6-15-1973 County Surveyor meas. random nail center inters roads at W 1/4 7 - 18 north. 2618.64 (+4.75) 2623.39 to W 1/4 7 nail then north 2631.39 to CIM at W 6-7 5254.78.

11-5-1973 County Surveyor meas. direct line from riser over D. Williams iron found. 10-3-73 to nail set on direct section line in line fence west at W 1/4 7. 2623.94. - Nail at W 1/4 7 to nail in line fence east at 1/16 N - nail at 1/16 North to CIM at west 6 - 7. 1318.45 + 1312.12 = 2630.57.

4-19-1974 County Surveyor set CIM over a 1/2" x 2' rod Corner falls on the East edge of the road. R.P.'s CSD PP #42680 NW 114.2' Conc. nail Cor. post W. 61.45 Punch hole S. end driveway C.M.P. NW 53.9

11-10-1982 County Surveyor at center of NW 1/4 found rocks where stake found in 1970. Removed rocks and dug down finding only remaining 4" of stake (down 1'). Shot from traverse pt. Left spike only at surface. Corner 7 south of E-W fence and 4' West of corner post to fence South; however, lines well with fence further South.

6-25-2007 County Surveyor found CIM down 0.3' leaning east. Removed CIM and found 1/2" rerod down 2.1' in good condition. Removed 1/2" rerod and set 6' telspar pipe w/cast iron cap down 0.5' at 1/2" rerod position.