Certificate of Location of Government Corner

ID#: 540804 **Description:** 1/4 SEC COR 8 17 54 **Date Set:** 10/25/1996 **County:** Olmsted

Section: 08 **Township:** 105N **Range:** 14W **Monument Description:** 1" square pipe with cap RLS #15809

Reference Ties:

The corner falls 3' west of centerline of CSAH 8 and in centerline of E-W twp road
County highway disk in PP #9991 NW 63.7'
County highway disk in PP #9992 SE 62.24'
County highway disk in TP brace post SW 45.87'
County highway disk in TP NE 63.18'
Ref pipe NE 64.16'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes Yerby 40.00 set temp 1/4 sect. post. West on true line between sect. 8 & 17 39.92-1/2 set a 1/4 sect. post in V 8'15'E mound of earth & sod, deposited charcoal made trench & pitts, planted Osage Orange seeds N+s.

8-1889 T. Fraser set stone boulder by midway and line, we dug for this stone but found that someone had dug here quite extensively and apparently did not find corner. We therefore set corner midway and line as per records. Set boulder 12x15x24

1936 county highway department Book 81, P. 54 had P.I. Near corner.

1959 County Highway Department had assumed corner, a short iron rod which was destroyed rod was 5.45' north and 2.8' east of corner as now located.

7-1964 J. Kerr drove 1/2" rod in black top from county references. Corner splits 4-way intersection. Old disc power pole NW No. 9991-63.7'

1-1969 County assumed corner.

8-6 & 7-1970 County surveyor run & meas. Line from SE 8 west over 1/2" rod in place. Also meas. From fence east at Center 8 area checking survey 80 rod line running west in SW Cor. Sec. 8 -Meas east 2611.72 - west to 41.7 offset 2659.05 - North to 1/16 fence 1314.1 - North to fence east at Center 8 2629.4 - dug thru blacktop to clean clay, found much old digging, stone gone all possibility of finding where it stood gone. Will run in M & L after setting SW Cor 8 from line north. Corner will come 5.45 S± & 2.81± y rod. County Notes B81 show corner as only point of PI only 0°1' 1936.

8-10-1970 County Surveyor found nothing, corner apparently destroyed. Set CIM over 3/4" x 15" pipe in blacktop (flush) Pulled rod set CIM M & L dug for stone

Fall, 1982 County Surveyor found CIM and shot. Drwg 5-17.

7-1-1996 County Highway Department found CIM with head broken.

7-2-1996 County Highway Department Angle @ Ref. Pipe. Angle Rt. P.K. in PP #9991 NW of Cor. To 1/4 Cor. 8-17 325° 38' 39", To 1/4 Cor 8-17 64.16.

7-3-1996 County Highway Department removed CIM before road resurfaced.

10-25-1996 County Highway Department set 1" square pipe w/cap at surface from 1996 overlay tie out.

7-28-2000 County Surveyor found 1" square pipe w/cap at surface in good condition.

2-26-2003 County Surveyor found 1" square pipe w/cap at surface in good condition.