Certificate of Location of Government Corner

ID#: 541004 **Description:** 1/4 SEC COR 10 15 54 **Date Set:** **County:** Olmsted

Section: 10 **Township:** 105N **Range:** 14W **Monument Description:** No monument - computed location

Reference Ties:

This corner falls on Rochester International Airport property

Corner History:

1853 Gov't Notes Yerby 40.00 Set temp 1/4 sect. post West on true line between sect. 10 & 15 40.00 set a 1/4 sect post in mound V 8°14'E of earth & sod deposited charcoal made trench & pitts planted Osage Orange seeds N & S.

6-1876 T. Hunter - T.H. Book 4 p. 132 unrecorded survey. 1/4 post missing, found where old fence post stood set by James Kelly by side of 1/4 post when said stake was standing - set marked stake just South of old post hole. Meas. East 39.90, meas. West 39.86-1/2, meas. North 19.97 - 19.97.

1957 McGhie & Betts Airport Survey set spike @ split of fences & shoulders of road. Set this point midway. 2633.9 E & W @ Sec. Cor. West. Set spike in centerline and line of fences. @ Sec. Cor. East Set 1/2" rod @ Sec. Cor. Measure north 2634.6 to pipe @ Center 10.

10-5-2007 County Surveyor visited area of corner. Found nothing.