Certificate of Location of Government Corner

ID#: 541106 **Description:** 1/4 SEC COR 10 11 54 **Date Set:** 6/15/1973 **County:** Olmsted

Section: 11 **Township:** 105N **Range:** 14W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 44' WNW of centerline of NBL of TH 63
400 m baseline monument SW 22.74'
Post w/sign 2' west
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes W.B. Yerby, Deputy Surveyor North between sections 10 and 11. 40.00 chs. Set a quarter section post in mound of earth and sod and deposited charcoal. Made trench and pits and planted osage orange seed North and South.

6-1876 T. Hunter Book 4 p. 132 unrecorded survey found stone in center of road set in old mound where original stake stood by James Kelly. Meas. N 19.93-1/2 - 19.93-1/2 Meas. W to Cen. 19.93-3/4 - 19.93-3/4.

11-1907 Charles Armstrong (P. 110 Book B), County Surveyor, set limestone 6"x6"x20" midway and on line.

1-6-1949 John Kerr found corner set 1" pipe over stone. MHD lost corner in TH 63 construction.

1965 John Kerr, County Surveyor, reset a CIM midway and on line.

9-2-1971 County Surveyor dug and found SW Cor 11 - (10-11-14-15) .2 N and 4.5' W of CIM as set (reset CIM destroyed old cor)

9-10-1971 County Surveyor dug and found recorded stone .55' South and 2.0' West of John Kerr's CIM.

This is a correction of a corner: Correct corner is .55' south and 2.0' West of John Kerr's CIM.

6-15-1973 County Surveyor dug down to stone and set a CIM over an iron rod over stone.

11-6-2002 County Surveyor found CIM down 0.5' in good condition.

4-28-2006 County Surveyor found CIM down 0.8' in good condition.