Certificate of Location of Government Corner

ID#: 541206 **Description:** 1/4 SEC COR 11 12 54 **Date Set:** 9/24/2007 **County:** Olmsted

Section: 12 **Township:** 105N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in line with fence west and in centerline of N-S twp road
This corner is located by GPS reference stations "Farmer A & B"

Corner History:

1853 Gov't Notes Yerby 40.00 set 1/4 sect. post in mound of earth & sod deposited charcoal. Made trench pitts planted Osage Orange seeds E & W of trench.

11-1907 Ch. Armstrong P.110 B S11 J. Kelly R. Thomas & others set temp point M & L 39.79 between sec. corners 2627.13 SE 11 assumed by rows of trees, NE 11 stone set by measurements. - West set iron pipe 30"x1" set M & L 20.12 (1327.9') this pipe came 1-1/2' SW of cor fences N & E.

9-1924 County Highway Department B43 P. 2 show Armstrong notes as iron stake. Meas. north 2624.7 - Sta. PI at S sec. 11-12. 5254.4. P.110 B shows temp point M & L 2627.13 stone north - assumed point midway tree rows south at 11-12-13-14 where 2 tree rows of cottonwood ran west 101 lks apart. - Note shows iron west as 1/16 M & L 1334.7 (R P110B) 1327.92 Sta. at 1-2-11-12 15 +78.3 making 5254.4 for mile south. (should try line from west again).

1966 or 67 J. Kerr dug & searched for 1/16 cor. pipe for line north, may have missed it but not likely. May have set 1/2" rod for assumed point for line north run line north 1/2 mile could not find 1/16 pipe west of NE Cor 11 which was found & referenced in 1950s.

9-8-1971 County Surveyor set nail in line of fence west and in center road N-S high grade. This corner in violent local dispute between Stoltenberg on the north and Nietz from on the south claim that fence once lay up to 15' north of where it now lays, ran & meas line from CIM over true stone at SW 11 east over nail set by County Highway Department accepted as N-S of 1/4 11-14 and rod .95' east of nail on same line accepted as final 1/4 11-14 set nail at 2680.83 from iron at 1/4 11-14 2681.15 E of SW 11.
- ran and meas. On random from above nail north over nail set as 1/4 11-12 area found nail at 2609.48 (R 2626.14) con't north to CIM at NE 11 line fell 6.2 east of CIM and total 5247.7 (R5252.28) Midway meas. 2623.85.

9-9-1971 County Surveyor ran aerial from CIM at 1/4 10-11 on 45' offset south over 45' offset south at CIM at Center 11. Note 1/4 10-11 later found true stone .55 south of CIM joint used so offset 44.45'. This line intersected east line sec. 11 26.88 south of nail or fence line running west. This line would be .55 too far south or 26.33 S of nail. This would make nail in line fence West at 2608.93 (R2626.14) actual midway 2623.85 or 14.92 to far S. - line at 1/16 west fell at 35.94 north of 45' offset south or 9.06 too far south (center corner post).
- corner post of new fence E-W-N came at 1343 east of CIM (Armstrong pipe below) (R 20.16) 1330.56 then 1333.3 east to nail in center road (direct line would be 3.1' west of nail or 1330.2 very near record.
- Dug at 1/16 from fence running north west over 15' to well west of 1330 and from fence running west over 10' north, could find no trace of pipe set by Armstrong but wires & more wires, set O.
-Did find post stub 12.2 east to N-S fence 9.5 South to EW fence. RP to nail at 1/4 11-12 orig nail 32.57 on transit line over nail head and center 1/16 corner post W.

11-19-1975 County Surveyor dug with backhoe at M & L location using post stub found 11-18-75 as Section Corner 11-12-13-14. Dug 6'/3'x8' to clay but found nothing. Road cut sharply on East side. Local RPs to trav. Pt: 11.91 N - 9.58 E nails.

9-12-1989 County Surveyor fd nail with head gone in center of N-S Rd & in line of fence west, probably nail set in 1971.

11-21-2003 County Surveyor found 60d spike down 0.3' in good condition.

9-24-2007 County Surveyor found 60d in good condition down 0.3', removed. Set 4' telspar pipe w/CIC down 0.45' from computed coordinates (nail was approximately 0.2' E of comp location).