Certificate of Location of Government Corner

ID#: 541409 **Description:** SEC CEN 14 54 **Date Set:** 7/23/2005 **County:** Olmsted

Section: 14 **Township:** 105N **Range:** 14W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.
1/2" pipe w/cap RLS #21940

Reference Ties:

The corner falls 4' west of centerline of N-S twp road and 9' north of centerline of twp road west
This corner is located by GPS reference stations "Chopp A & B"

Corner History:

5-13-1874 T. Hunter P. 244 No. 245 set marked stake at inters 1/4 lines as corners set up for 1/4 corners (all 1/4 corners gone at this survey) - 16 west set marked stake M & L 20.11 (1327.26.

7-1968 J. Kerr after finding orig W 1/4 cor west set M & L p. 244 (sleigh shoe & stone). Meas. east on line of found 1/4 14-15 and fence terminal N-S-E at 1/4 13-14 (land east now common land - both east of center 14 and east of 1/4 13-14 but land east of 1/4 13-14 was separate parcels so assumed fence east as orig line. This E-W 1/4 line hits centerline road nicely. -16 W dug extensively 4'x4'x8' for 1/16 stake - clean black soil - found one spot appeared as real dark hole at 1325.72 from W 1/4 Cor. Record = 1327.26. 1.6' short record 1874. This came only .9' north of E-W 1/4 line set up above. Set long pipe as 1/16 cor. came in center road. MHD disc in tele pole NW 80.3 - bottle cap in PP N 93.8 corner comes about 3' east of fence north which explains McGhie's assumed corner at W 1/4 14 being 4.2' west of stone. At center 14 set rod at 26251.5 on 1/4 line set up. There is a random rod set on 1/4 line in center road opposite center field drives on crest west 300'± down 1"±.

1974 County Surveyor, R.P.'s C.H. Disc N.W. side P.P. #9454 S.W. - 69.8', C.S.D. SW side stub tele pole NW 45.64, CSD South side PP E 35.77

7-22-1974 County Surveyor dug - found nothing - road cut. Reset J. Kerr rod & took above R.P.s for center 14.

11-21-1975 County Surveyor center Dug from nail 12'E and 10'N to clay (3') but found nothing.

11-26-1975 County Surveyor, 1/16 West Dug with backhoe to corner point 4'N and 5'E of John Kerr's corner. Much black dirt but found nothing. 1' of frost in road - hard digging! Did not get directly N of Kerr's corner.

9-24-1984 County Surveyor found 5/8" rod at road surface but it did not fit R.P.'s taken in 7-22-1974. Set spike at intersection of tie to pole East and pole stub NW and came .15 W and .24 N of rod (but tie to pole SW still .11 long. Shot rod as is from West.

11-1-1984, County Surveyor center 14: Dug as follows: Dug 3' deep, 1' of road fill, then 2' of coarse rock to clean clay, area probably old frost boil. Only extreme West edge of hole had skiff of black dirt. Digging on Hunter measure from North and West.

11-1-1984 County Surveyor, 1/16th West of Center 14: Dug as follows: Dug 4' deep to clay. Much black dirt. Old diggings not quite to clay. Found good stake hole beneath black dirt at clay line. Followed down 6". Good topper and pieces of wood. Drove a 5/8" re-rod in stake hole and threw crushed rock around it. Set reddish colored small boulder on top of iron & spike on road surface.

11-20-2003 County Surveyor found 5/8" rerod down 0.2'. Monument falls 5.0' West of centerline of 2nd Ave SE and 3.0' South of centerline of 85th St SE.

7-23-2005 GGG, Inc. set pipe w/cap RLS #21940 at intersecting quarter lines.

6-25-2007 County Surveyor found 1/2" pipe w/cap down 0.1' in good condition. Removed 5/8" rerod.