Certificate of Location of Government Corner

ID#: 541804 **Description:** 1/4 SEC COR 18 19 54 **Date Set:** 9/25/2007 **County:** Olmsted

Section: 18 **Township:** 105N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 14 1/2' south of centerline of TH 30 and 1/2' west of fence north
PK in top of N headwall of large concrete culvert NE 81.80'
PK in top of S headwall of large concrete culvert ESE 74.83'
This corner is located by GPS reference stations "Oehlke A & B"

Corner History:

Gov't Notes Yerby 1853 40.00 set temp 1/4 sect. post Course N 89°30'E on true line between 18 & 19 39.10 set a 1/4 sect. Post in mound of earth & sod deposited charcoal made trench & pitts planted Osage Orange seed N & S.

10-1888 T. Hunter p. 425 No. 414 found stone boulder P. 245 in center of road. - 16 east set stake M & L 20.01, - 16 south set stone M & L 20.04, - 16 center NE 1/4 19 set stake M & L 19.97-1/2 on E-W 1/16 line.

5-1874 T. Hunter P. 245 No. 246 found stone boulder in middle road set by Ole Oleson & other when road was opened and stake standing in mound. - 16 west meas. Line carefully 38.68 (2552.88) record 39.10, set stake west of 1/4 cor on line at 19.78-1/2 then 18.89-1/2 to sec. Cor. Which is boulder 8 x 12 x 15 set this survey in place stake found. - 16 north set stake M & L 19.93 (1315.38).

MHD const. Notes: (2564.0 MHD P/W Map. - probably shorter as line is kinked.)
Sta. 347 + 98.9 or 2563.9 from Sta. West on twp line (1874 Hunter 2552.88) took line of fences N & S. Centerline highway as const. Lies 15.2' north of assumed section line - likely center old road.

10-18-1982 County Surveyor dug centered over nail set in line with fence North and 15' So. Centerline TH 30 found 6" x 13" x 22" boulder standing beneath old road. Top down 8'. There was no stake. Stone standing in 2' of black dirt but still appears to be some black mark in clay. Set irons around stone. Digging at bottom of hole extends from stone 2' West, 1' South, and 4' East. Stone .08N and .55W. Of t.n. (t.n. NW 18.94 NE 21.90 stone NW 18.55 NE 22.25.)

10-21-1982 County Surveyor, 1/16 East: Dug on North shoulder of TH 30 centered over a point on line from the stone fd. At 1/4 Cor. 18 - 19 to Kerr's iron @ Sec. Cor. 17-18-19-20 and @ Hunter's measure from the stone fd. @ 1/4 Cor. 18-19. Area disturbed by road construction. Found nothing.

11-8-1982 County Surveyor set a CIM over a 1/2" x 18" rod over the stone found 10-18-1982. The corner 1/2' West of the line of the fence North (fence line South mostly gone but what's left lines with corner) and 14.9 South of centerline TH 30 RP's: P.K. in top of N Headwall of large concrete culvert NE 81.80, P.K. in top of S Headwall of large concrete culvert ESE 74.83 (Both of these P.K.'s above W'ly wall of actual culvert.)

11-15-1982 County Surveyor diggings here settled so bad after heavy rain we had to remove CIM and iron beneath they were so loose.

4-21-2004 County Surveyor visited area of corner. Found nothing. Pk nail in north headwall gone.

9-25-2007 County Surveyor set 5' telspar pipe w/cast iron cap down 0.4' from GPS and traverse data.