Certificate of Location of Government Corner

ID#: 541904 **Description:** 1/4 SEC COR 19 30 54 **Date Set:** 11/3/2011 **County:** Olmsted

Section: 19 **Township:** 105N **Range:** 14W **Monument Description:** Cast Iron Monument

Reference Ties:

The monument falls in a cultivated field with waterway to the east.
The monument is down 1.3'
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes William B. Yerby, Deputy Surveyor Course N89°55'E on true line between 19 and 30. 39.80 chs. Set a quarter section post. Br. Oak 4 in. N5°E 198 lks. Br. Oak 10 in. S15°E 46 lks. 79.80 chs. To section corner.

10-9-1888 Thomas Hunter, County Surveyor, (Book A, Page 425, No. 414) "Quarter corner missing and both witness trees gone, and coming in cultivated ground which had been plowed and worked for years, search for the corner was useless. Set corner stake driven deep with stone by its side on line and Gov't measure.

6-4-1892 Thomas Fraser, County Surveyor, by William Fraser, Deputy, (Book A, Page 480, No. 457, and Old Fieldbook 8, Page 25) "Found as planted and described by Thomas Hunter in Survey 414--Page 425." He found Hunter's stone at the 1/16 West (no measure given). He set the 1/16 South of 1/4 Cor. 19-30, a stone boulder midway (19.96&7/8 chs.) and on line to the center 30 where he found stone as planted by Hunter in Survey No. 414."

1968 John Kerr, County Surveyor, (Kerr Book 96, Page 76, and Kerr Book 98, Page 33, and Card) measured 2628.8 from stone found at Sec. Cor. 19-20-29-30 to 4" pipe corner post at 1/4 Cor. 19-30.

1971 County Surveyor found stone at the center 30. Dug for the 1/16 North of the center 30 and for 1/4 Cor. 30-31 but could not find corners. Found a pointed boulder at the 1/16 West of 1/4 Cor. 19-30 and found stone at W Sec. Cor. 19-30. Used line from 4" pipe corner post at 1/4 Cor. 19-30 over stone found at the center 30 to set the S 1/4 Cor. 30.

1973 County Surveyor set a point at the center 19 on line and at prorated Thomas Hunter measure from the W 1/4 Cor. 19 over Hunter's stone found at the 1/16 East (See Hunter's Survey No. 414, Page 425, Book A). Point came over large boulder--did not dig.

10-1982 County Surveyor dug at 1/4 Cor. 18-19 and found stone. Dug at the 1/16 South of 1/4 Cor. 18-19 but could not find Hunter's corner. Dug at the 1/16 North of 1/4 Cor. 19-30 and found the mark of an old stake.

11-16-1982 County Surveyor set a 1" rod as the corner in hole drilled in concrete around 4" pipe corner post. Iron .6 NE'ly of post. The corner is set at the intersection of the line from the N 1/4 Cor. 19 (stone found) over the stake mark found at the 1/16 North of 1/4 Cor. 19-30, and the line from W Sec. Cor. 19-30 over the boulder found at the 1/16 East in 1971. Corner set is .51 North of the straight line between sec. Corners.

10-15-1996 Roger Brand Associates found and used monument.

5-11-2006 Massey Land Surveying found and used 1" rod at quarter corner.

10-20-2010 County survey crew found 1" rod in good condition.

11-3-2011 County survey crew found 1" iron rod in concrete. The rod is in danger of being damaged by farm equipment so it was removed and replaced with a 1/2" x 15" iron rod with a cast iron monument set above it. The cast iron monument is down 1.3'