Certificate of Location of Government Corner

ID#: 542004 **Description:** 1/4 SEC COR 20 29 54 **Date Set:** 9/22/1982 **County:** Olmsted

Section: 20 **Township:** 105N **Range:** 14W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls in centerline of CSAH 8 and in line with fence east
Concrete nail in knot in NW side PP #11433 NE 78.65'
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes William B. Yerby, Deputy Surveyor West on line between sections 20 and 29. 39.95 chs. Set a quarter section post in mound of earth and sod. Deposited charcoal. Made trench and pits. Planted Osage orange seed N & S. 79.90 chs. To section corner.

10-1857 E.P. Bircher, Surveyor, per J.B. Fellows, Deputy, (Old Road Book, Road No. 92) surveyed a road running North and South from this corner.

5-1870 Robert Perry, County Surveyor, per Thomas Hunter, Deputy Surveyor, (Book A, Page 177, No. 188) "Sluice built over this stake, the center of which is said by Mr. Rogers who helped build it to be exactly over the original mound and 1/4 post." He measured West 39.81 chs. To Sec. Cor. 19-20-29-30, a stake found, and 39.86 East to Sec. Cor. 20-21-28-29, a stake found. (He shows a 15' deflection to the North going East at the corner.) He used the corner to set the 1/16 North, a stake, equidistant (20.20 chs.) to the Center 20, a stake, set at intersecting 1/4 lines.

8-1903 Robert Fraser (Old Fieldbook 10, Pages 19 and 20) "Ran C (NW Cor. 29) and A (NE Cor. 29). Came North 5 links and short 34 1/2 links." Gives no description of corner but set the 1/16 West and the 1/16 East and possibly the 1/16 South. He found a stone at the Center 29.

1959 county highway department found boulder with cross. RPs- spike in tele pole NW 34.96, spike in pp NE 75.17, spike in corner post E 33.28.

1962 County Highway Department (C.H.D. Book 202) calls for "x on boulder" at the corner.

11-30-1972 County Surveyor dug with jackhammer. Found 2" to 3" cross cut in a large flat boulder 3.2 deep in center road and a little South of woven wire fence East. Set iron riser. RPs- NE to conc nail in knot on NW side PP #11433 up 6', 100.0 about 2' N of E to 7/16x4' smooth rod up 2" about 8" N of high woven wire fence.

8-8-1978 County Surveyor dug at the 1/16 North and at the Center 20 but did not find anything.

9-22-1982 County Surveyor found a R.R. spike under new blacktop on CR 8. Removed R.R. spike and dug down to iron set 1972 (down 6"). Iron a re-rod and was .06 North and .09 East of the R.R. spike location. Set a CIM over a 5/8" rod at the location of the rod set over the stone in 1972.

2-26-2003 County Surveyor found CIM down 0.3' in good condition.