Certificate of Location of Government Corner

ID#: 542106 **Description:** 1/4 SEC COR 20 21 54 **Date Set:** 7/14/2004 **County:** Olmsted

Section: 21 **Township:** 105N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 2' north of centerline of E-W twp road
Minnesota Highway Disk in fence post NE 34.8'
Minnesota Highway Disk in fence post NW 24.8'
Minnesota Highway Disk in fence post SW 35.7'
Minnesota Highway Disk in PP #11458 S 22.0'
Post w/sign 10' north
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, Yerby; 40.0 set a 1/4 section post in mound of earth, sod, deposited charcoal, made trench with pits, and planted osage orange seed E & W.

5-1870 R. Perry by T. Hunter Pg.177 No.188; Found stake standing.

4-1896 W.Fraser Pg.594, No.540; Corner considered lost. Set stone 3x6x22 M & L.

1960 MHD, DuVal, found stone and set iron riser.

6-1968 J. Kerr found limestone with 5/8" rod above. Set CIM with 1"x2' pipe on each side of stone as true corner. RPs- MHD disc in fence post NE 34.8, MHD disc in fence post NW 24.8, MHD disc in fence post SW 35.7, MHD disc in PP #11458 on NW side pole 22.0, corner lies center road 1' west of fence line south.

10-1982 County Surveyor found CIM in good condition.

3-4-2004 Vince Fangman found broken monument at this corner.

7-12-2004 County Surveyor found CIM without head down 0.4' in good condition.

7-14-2004 County Surveyor removed CIM and found 1" pipe down 2.2' in good condition with limestone on west side. Removed 1" pipe and limestone and set 7' telspar pipe w/cast iron cap down 0.4'. Set post with sign 10' north.