Certificate of Location of Government Corner

ID#: 542109 **Description:** SEC CEN 21 54 **Date Set:** 7/24/1972 **County:** Olmsted

Section: 21 **Township:** 105N **Range:** 14W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.

Cast Iron Monument

Reference Ties:

The corner falls 2' west of centerline of twp road north and 6' north of centerline of twp road west
The monument is down 0.7'
Bottle cap in PP #11468 SW 48.92'
Center of S headwall RCP (badly broken) SW 37.25'
Punch hole in S end 24" CMP SE 36.06'
Punch hole in N end 24" CMP ESE 29.62'
This corner is located by GPS measurement

Corner History:

4-4-1896 W. Fraser, County Surveyor, (Book A, Page 594, Survey No. 540) set a stone at intersecting quarter lines and also a sixteenth stone west M&L at 19.91 3/4 chains (1314.55').

6-17-1968 J. Kerr, County Surveyor, dug for stone and found nothing. Set a Cast Iron Monument over 1 1/4" pipe at intersecting quarter lines and took references. RPs - Bottle cap in PP #11468 SW 49.2', Center south headwall RCP SW 37.15', Center 18" cottonwood ENE 57.0', Punched cross in South end 30" CMP SE 33.67'. The corner lies in center N-S roads. Did not look for 1/16th stone west.

7-24-1972 R. Brand, County Surveyor, dug and found the 3"x10"x? limestone 1.9' W and 1.4' N of J. Kerr's Cast Iron Monument. Removed Kerr's CIM and reset CIM over limestone and updated references. RPs - Bottle cap in PP #11468 SW 48.92', Center of the S headwall of RCP (badly broken) SW 37.25', Punch hole in the S end of 24" CMP SE 36.06', Punch hole in the N end of 24" CMP ESE 29.62'.

Note: This is a correction of corner as set by J. Kerr. W. Fraser's stone as found by the County Surveyor lies 1.9' West and 1.4' North of the CIM set at intersecting 1/4 lines. He also found the sixteenth stone West as set by W. Fraser at 1314.8'.

9-23-1982 County Surveyor found and shot Cast Iron Monument.

10-11-1995 McGhie & Betts, Inc. found and used Cast Iron Monument for Airport survey.

3-4-2004 V. Fangman found and used Cast Iron Monument.

7-12-2004 County Survey Crew found Cast Iron Monument down 0.7' in good condition and measured its position using GPS.