Certificate of Location of Government Corner

ID#: 542204 **Description:** 1/4 SEC COR 22 27 54 **Date Set:** 10/15/2007 **County:** Olmsted

Section: 22 **Township:** 105N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is down 0.2'
The corner falls 30 1/2' west of centerline of SBL of TH 63 and 228' north of centerline of Schumann Dr NW
County Survey Disk in NE side PP NW 109.88'
This corner is located by GPS reference stations "Midwest Breeders A & B"

Corner History:

1853 Gov't Notes, Yerby; 40.0 set temp 1/4 section post west on true line between section 22 & 27. 40.12 1/2 set a 1/4 section post in mound of earth, sod charcoal, made trench, pits, and planted osage orange seeds N & S.

8-1899 W. Fraser Bk. A pg. 659 Reset the stone midway and on line at 2651.88' in line of the fence West as testified by the settlers.

12-1910 Ch. Larson Bk. B. pg. 146 Found a stone boulder.

3-1973 County Surveyor reset the corner midway and on line at 2651.77' with a 3/4" by 30" bolt as the corner. RPs- corner is 16.75 due west of MHD PK 18.75 from Conc., 95.85 SW to center no plate PP #11001, 148.53 NNW to top center S edge S end 24" farm drive culv..

3-1997 GGG says no monument at N 1/4 27 or center 27. Called Mn/DOT but they have no ties.

7-1-2002 County Surveyor found nothing at corner location. Set two points to GPS to relocate corner.

11-13-2002 County Surveyor set 1" square pipe w/cap at M & L bridge bolt location from 1973 survey.

10-15-2007 County Surveyor found 1" square pipe w/cap down 1.2' in good condition. Removed 1" square pipe w/cap and set 5 1/2' telspar pipe w/cast iron cap down 0.2'.

11-2-2011 County survey crew found cast iron cap in good condition