Certificate of Location of Government Corner

ID#: 542305 **Description:** SEC COR 22 23 26 27 54 **Date Set:** 7/12/2002 **County:** Olmsted

Section: 23 **Township:** 105N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 3' west of N-S fence and 14 1/2' south of fence east
Post w/sign 2' SW
This corner is located by GPS reference stations "Bugy A & B"

Corner History:

1853 Gov't Notes, Yerby; 80.0 set post-corner to section 22-23-26-27. RPs- 10" burr oak N68 W338 links, 42" burr oak S52 E207 links, 12" burr oak S60 W343 links and made trench.

1899 W. Fraser (BK. A pg. 659 No. 587) reset a stake by the measurements N and S. RPs- 10" burr oak S 153 links, 10" burr S 26 1/2°W 149 1/4 links.

4-1906 C. Armstrong (BK. B pg. 108) sec. 26. Claim stones found at all 4 corners of NW 1/4 26. Also, shows same two witness trees at NW 26, 10" burr oak S 156 links, 102.96, 10" burr oak S 26 1/2°W 149 links 98.34.

1910 C. Larson (BK. B pg. 146) Sec. 27 found the corner. Oak stake.

9-10-1971 County Surveyor set 1 1/2"x4 1/2' iron pipe. Corner lies 3'W of N-S fence and 14.7 SSW of corner post of fences N & E.

3-23-1981 County Surveyor set sign and post 0.45' North of inplace pipe fence running East is now in line with corner.

7-1-2002 County Surveyor found pipe in poor condition.

7-12-2002 County Surveyor removed pipe and set a 6' telspar pipe with cast iron cap.