Certificate of Location of Government Corner

ID#: 542405 **Description:** SEC COR 23 24 25 26 54 **Date Set:** 1/17/2002 **County:** Olmsted

Section: 24 **Township:** 105N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

Lightly blazed 9" Ironwood NNW 29.7'
Large Elm WNW 31.0'
Post w/sign 2' south
This corner is located by GPS reference stations "Dux A & B"

Corner History:

1853 Gov't Notes, Yerby; 80.0 set post-corner to section 23-24-25-26. RP- 20" Elm S32 W157 links and made trench.

1899 W. Fraser (BK. A pg. 659) found the corner gone so he reset a 2"x8"x23" limestone from the southwest witness stump.

1938 county highway department (BK. 103 pg. 5) found the limestone with a stake on the north side. RPs- spike in 20" maple WNW 31.0, spike in 8" boxelder SW 37.3, 12" elm fence terminal 2' south & 6' east.

8-30-1971 County Surveyor found the original limestone. Set U shaped steel fence post on south side stone. RPs- 29.7 NNW to blazed 9" iron wood on higher ground, 31.0 WNW to tree used by county highway department as RP in 1938, 37.0 SW to half dead 16" boxelder with very line sucker used by county highway department as 8" boxelder 1938, found elm stated as fences N & E about 18".

1-17-2002 County Surveyor found limestone down 3'. Removed stone and set 6' telspar with cast iron cap up 0.2'.