Certificate of Location of Government Corner

ID#: 542604 **Description:** 1/4 SEC COR 26 35 54 **Date Set:** 9/1/1971 **County:** Olmsted

Section: 26 **Township:** 105N **Range:** 14W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 1 1/2' west of centerline of N-S twp road
40d nail in S side 18" Burr Oak W 62.13'
County highway disk in PP #10983 SSE 95.88'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, Yerby; 40.0 set temp 1/4 section post west on true line between sections 26 & 35. 39.95 set a 1/4 section post. RPs- 14" burr oak N42 W127, 12" burr Oak S75 W215.

6-1899 W. Fraser (BK. A pg. 659) Sec. 26 found the stake and stone in the center of the road.

12-1910 CH. Larson found stake.

10-1924 county highway department used stone as P.I. of road.

7-1930 county highway department (BK. 57 pg. 41) found the stone in the center of the road. RPs- fence post NE 65.8, TP SE 59.8.

9-1-1971 County Surveyor set CIM over small pipe. dug extensively with tractor over large area but could not find stone. Reset corner by county highway department R.P. in Oak tree West and Meas. South from center Sec. 26. RPs- 95.88 SSE to county highway department disc in PP #10988, 62.13 due west to 40d center S side 18" burr oak

7-22-1997 County Surveyor found CIM down 1' in good condition in N-S 15th Ave 1 1/2' W of centerline and at 95.92 to 1971 pole tie SE PP #10983.

2-17-1998 County Surveyor found CIM in good condition.

1-19-2001 County Surveyor found CIM down 1.1' in good condition.