Certificate of Location of Government Corner

ID#: 542606 **Description:** 1/4 SEC COR 26 27 54 **Date Set:** 9/28/2000 **County:** Olmsted

Section: 26 **Township:** 105N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 13' south of centerline of CR 120 and 34 1/2' west of bridge deck
Center 36" Ash NNE 151.8'
Traverse pt "WTF" NW 233.64'
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes W.B. Yerby, Deputy Surveyor North between sections 26 and 27. 40.00 chs. Set a quarter section post. Ash 8 in. N28W 82 lks. Elm 10 in. S69E 294 lks.

6-1892 Thomas Fraser (P. 488 No. 463), County Surveyor, states corner gone. Reset corner from SE bearing tree still standing.

6-1899 William Fraser (P. 659 No. 587), County Surveyor, found stake and stone set in previous survey from S.E. witness tree still standing.

12-1910 Charles Larson (P. 146 B), County Surveyor, located corner by witness (L. Duncanson) and by bearing tree.

8-1971 County Surveyor dug area of corner but found nothing of stone or stake. Set a steel fence post in road below surface as corner using measure and line from E. 1/4 Cor. 25-26 over Center 26. RPs to stee post- 10.66 4' W of S to DR Pepper cap on E side corner post of short fence running Swly, 61.52 SE to pepsi cap in SW side PP #44222, 88.5 NNW to large 28" ash center, 151.8 NNE to center 36" ash, corner lies about 153+ west of edge concrete floor of bridge and at edge of grass on S edge of road.

7-23-1974 County Surveyor removed steel post and set CIM over 1" pipe as corner.

3-1997 GGG reports 1/2" iron at corner.

7-21-1997 1/16th west: County Surveyor found 1/2" rerod in good condition.

7-22-1997 County Surveyor found 1/2" rerod over CIM. Top of CIM 26" deep on ditch slope on south side CR 120. Set 1" square pipe/cap over CIM. The corner falls 12' south of centerline CR 120 & 5 1/2' east of stub fence south.

5-14-1999 County Surveyor found 1" square pipe w/cap in good condition. Tied out corner.

6-10-1999 1/16th west 1/4 cor 26-27. County Surveyor found 1/2" rerod in good condition and tied out corner.

9-28-2000 County Surveyor set 1" square pipe w/cap at surface from 1999 tie out.

9-28-2000 1/16th west 1/4 cor 26-27. County Surveyor set survey marker nail at surface from 1999 tie out.

6-19-2002 County Surveyor found 1" square pipe w/cap at surface in good condition.

5-7-2007 County Surveyor found 1" square pipe w/cap at surface in good condition.