Certificate of Location of Government Corner

ID#: 542804 **Description:** 1/4 SEC COR 28 33 54 **Date Set:** 10/25/1996 **County:** Olmsted

Section: 28 **Township:** 105N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 1' south of centerline of CSAH 35 and in line with fence north
Ref pipe WNW 274.48'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, Yerby; 40.0 set temp 1/4 section post west on true line between sections 28-33. 39.95 set a 1/4 section post. RPs- 12" burr oak N73 E356 links, 12" burr oak S82, W97 links.

6-1892 T.Fraser Pg.491 No.465; Found witness tree, but no corner. Planted marked boulder as corner from US Field Notes.

10-1904 C.Armstrong Pg.94 B; Corner gone.

1966 county highway department Bk.321; Assumed corner set 3/4" reinforced rod. RPs- spike & disc in TP NW 61.3, soike & disc SW 102.14.

11-1976 5/8" capped pipe set by McGhie & Betts at County Surveyor corner location.

7-1996 County Surveyor found 3/4" pipe. Set reference pipe on east side Pila driveway in SW 1/4 28. Centerline CR 35 south 55 1/2' center line driveway W 12'. Removed pipe.

10-25-1996 county highway department set 1" square pipe w/cap at surface from 1996 overlay tie out.

11-09-2001 County Surveyor found 1" square pipe w/cap at surface in good condition.