Certificate of Location of Government Corner

ID#: 542805 **Description:** SEC COR 28 29 32 33 54 **Date Set:** 10/25/1996 **County:** Olmsted

Section: 28 **Township:** 105N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CSAH 35 and in line with tree line north
County Survey Disk in CP NNE 51.66'
County Survey Disk in TP S 141.78'
County Survey Disk in N side east gate post SE 92.83'
Punch hole in W end 18" CMP SE 67.37'
County Survey Disk in E side PP #1087 SSW 51.99'
County Survey Disk in TP NW 134.96'
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes W.A. Yerby, Deputy Surveyor 80.00 set post to sec 28-29-32-33 Made trench. Burr Oak 10 in N 62 E 2.76 links, Burr Oak 14 in S 10 W 199 links.

6-1892 Thomas Fraser (P. 491 No. 465), County Surveyor, could find no trace of corner. Set boulder as corner by double proportionate measure from NW Sec. Cor. 28 to SW Cor. Sec. 33 and S 1/4 Cor. 28 to SW Cor. Sec. 29.

1903 Robert Fraser (old fieldbook No. 10 P. 19), County Surveyor, measured from S 1/4 Cor. 29 to Sec. Cor. 28-29-32-33.

10-1904 Charles Armstrong (P. 94B), County Surveyor, found boulder P. 491.

1958 M.H.D. dug down 3' to 4' but found nothing. Used centerline of gravel road and the line of fence North to locate corner. Set iron rod.

1966 County Highway Department (B. 321) used corner set by M.H.D. RPs- 3/4" rod over spike 60d, spike & disc corner post N 35.37, spike & disc corner fence post SE 82.65, spike & disc PP SSW 52.03.

5-1975 County Surveyor found 3/4" rod in road.

11-18-1975 County Surveyor set CIM over 3/4"x10" rod over found stone with cross on top. RPs- CSD W side corner post NNE 51.66, CSD E side PP #10873 SSW 51.99, punch hole top W end 18" CMP to field drive S SW 67.37, CSD N side of E gate post to field drive south SE 92.83, CSD S side TP NE 141.78.

10-1994 County Surveyor found CIM in good condition.

7-1996 County Surveyor found CIM in good condition and set reference pipe w/cap on west edge field drive in NW 1/4 Section 33. Centerline CR 35 N 29 1/2, centerline field drive east 11'. Removed CIM.

10-25-1996 County Surveyor, county highway department set 1" square pipe w/cap at surface from 1996 overlay tie out.

11-09-2001 County Surveyor found 1" square pipe w/cap at surface in good condition.