Certificate of Location of Government Corner

ID#: 542904 **Description:** 1/4 SEC COR 29 32 54 **Date Set:** 10/25/1996 **County:** Olmsted

Section: 29 **Township:** 105N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CSAH 8 north and in centerline of CSAH 35
County highway disk in PP SE 58.5'
Punched cross in culvert SW 55.61'
Punched cross in culvert NW 52.59'
Ref pipe SSE 89.39'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes: Yerby west on a true line between sec. 29 & 32 40.20 set 1/4 sec. post in mound of earth and sod. Deposited charcoal, made trench and pitts. Planted Osage Orange seed N & S.

1903 R.Fraser Old Fieldbook No.10 Pg.19; No desc of corner , but sure used & checked corner stone at center 29.

1960 MHD found stone 2' deep with hub riser. Four references all removed from area in county grading. County referenced before grading B321.

1966 county highway department Bk.321; found 1/2" rod.

6-7-1968 J.Kerr placed 1/2" rod by County references and added new references; disc in PP SE 58.5, cross in top culv. SW 55.61, cross in top culv NW 52.59.

10-26-1994 County Surveyor found 1/2" iron in good shape in intersection of CR 35 and CR 8.

7-25-1996 County Surveyor found 5/8" iron rod by J.Kerr. Set reference pipe on E edge 44th Ave SW in NE 1/4 Sec.32, centerline 44th Ave SW W 7 1/2', centerline CR 8 & 35 N 89'. Removed iron.

10-25-1996 County Surveyor, county highway department set 1" square pipe w/cap at surface from 1996 overlay tie out.

11-09-2001 County Surveyor found 1" square pipe w/cap at surface in good condition.

2-26-2003 County Surveyor found 1" square pipe with broken cap at surface in good condition. Replaced cap.