Certificate of Location of Government Corner

ID#: 543206 **Description:** 1/4 SEC COR 31 32 54 **Date Set:** 8/31/2007 **County:** Olmsted

Section: 32 **Township:** 105N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 21 1/2' south of centerline of trail
County Survey Disk in E side 24" Maple SE 12.35'
County Survey Disk in S side 24" Box Elder W 26.45'
Post w/sign 2' south
This corner is located by GPS reference stations "Shovel A & B"

Corner History:

10-1853 Gov't Notes William B. Yerby, Deputy Surveyor North between Sec 31-32 40.00 chs. Set a quarter section post. Burr Oak 12" N 80° W 210 lks. Burr Oak 10" N 51° E 313 lks.

4-1884 Thomas Hunter (Page 388 No. 379) County Surveyor witness trees all gone and no stumps could be found that could be identified as such. We however found stake and pole standing at the corner of a post and rail fence running east and south, which Mr. S. W. Riese an old settler says the original corner stood until recently. So we accepted the stake found as the corner for the purposes of this survey.

12-1915 John Kerr, County Surveyor, ran from SE Cor 31 as established in this survey to the NE Cor Sec 31, a stone found. He then set the 1/4 Cor of 31-32 midway and on line between section corners (measure each 1/2 mile = 2635.9)

5-9-1973 County Surveyor set 3/4" x 4' long pipe up 16" as corner with electric fence post on south side. Corner in flood plane with washed out high water channels east and south. RPs-82.0 6' N of E to 60d south side leaning 16" box elder, corner under what fence is left.

11-13-2001 County Surveyor found 3/4" pipe up 3'.

1-15-2002 County Surveyor cut off 3/4" pipe. Set 4' telspar pipe with cast iron cap over pipe up 0.3'.

5-7-2007 County Surveyor found telspar pipe w/CIC up 0.4' leaning east.

8-31-2007 County Surveyor removed leaning cast iron cap on telspar pipe and set a 5' telspar pipe w/CIC up 0.2' from GPS coordinates.