Certificate of Location of Government Corner

ID#: 543304 **Description:** S 1/4 SEC COR 33 54 **Date Set:** 9/21/2007 **County:** Olmsted

Section: 33 **Township:** 105N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 7' north of centerline of CSAH 6 and 27' east of centerline of field entrance north
County Survey Disk in NE side PP SE 87.68'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes West on south boundary of Section 33. 40.00 chs. Set quarter section post. Made mound with trench and drove charred stake in center and planted apple seed in NW corner.

10-22-1904 Charles Armstong, County Surveyor, (P. 94B) found limestone.

7-1974 Olmsted County Surveyor dug with backhoe but found nothing.

5-22-1975 County Surveyor set CIM over 5/8" x 13" rod on line from SW corner Section 33 over NW corner Section 3 and midway from SW corner Section 33 to SE corner Section 33. Corner lies in CR 6 5 1/2 N centerline and 12" E centerline filed drive N. RPs- punch hole top center E end field drive culvert N 18.42', punch hole top center W end field drive culvert NW 30.01, CSD in S side PP #11048 NE 103.35'.

5-22-1975 County Surveyor set pipes on property line of County Park property at 27.5' north of CIM - pipe, 162.65 north of CIM - wood stake, 287.0' north of CIM - pipe, bank of river falls 302' north of CIM. RPs to pipe 287' north of CIM- CSD disc 7 spike S side 18" boxelder E 28.49, CSD disc & spike NE side 30" elm SE 18.65.

5-22-1975 County Surveyor set 1 1/4"x18" pipe on east line of County Park property 26.04' North of RR spike set as property corner. Pipe falls 5' south of river bank.

11-6-2001 County survey crew found CIM down 0.6' in good condition.

9-30-2005 County survey crew found CIM down 0.6' in good condition.

7-25-2006 County survey crew found CIM down 0.6' in good condition. Tied out corner for 2006 road construction.

8-23-2006 County survey crew removed CIM for road construction. Found 5/8" rerod down 2.4' in good condition and removed.

9-21-2007 County survey crew set 1" square pipe w/cap at surface from 2006 construction tie out.