Certificate of Location of Government Corner

ID#: 543305 **Description:** S SEC COR 32 33 54 **Date Set:** 9/21/2007 **County:** Olmsted

Section: 33 **Township:** 105N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CSAH 6 and 13' west of centerline of field entrance north
County Survey Disk in NW side PP NE 83.14'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes West on South boundary of section 33. 80.00 chs. Set post for corner to sections 32 and 33. Made mound with trench and drove charred stake in center and planted apple seed in NW corner.

5-1878 Tom Hunter (P. 343 No. 337), County Surveyor, states corner missing, set a stone 7"x8"x21" at 1/3 distance of S 1/4 corner Sec. 32 to SE corner 33. Corner fell in middle of road.

10-1904 Charles Armstrong (P. 94 Book B), County Surveyor, found limestone in road set by T. Hunter 33' south of row of trees running east and about 6' west of fence running north.

7-27-1974 County Surveyor drove a 3/4"x3' iron rod on the south side and set a CIM over the stone flush with the Bit. Surface of CR 6. RPs- punch hole in W end 18" CMP N 24.57, CSD SW side PP #11038 NW 106.5.

10-26-1994 County Surveyor found CIM in good shape.

11-6-2001 County Surveyor found CIM down 0.4' in good condition.

9-30-2005 County Surveyor found CIM down 0.5' in good condition.

7-26-2006 County Surveyor found CIM down 0.5' in good condition. Tied out corner for 2006 road construction.

8-23-2006 County Surveyor removed CIM for road construction. Found stone down 3.3' in good condition.

9-21-2007 County Surveyor set 1" square pipe w/cap at surface from 2006 construction tie out.