# Certificate of Location of Government Corner

**ID#:** 543404 **Description:** S 1/4 SEC COR 34 54 **Date Set:** 7/2/2007 **County:** Olmsted

**Section:** 34 **Township:** 105N **Range:** 14W **Monument Description:** MNDOT survey monument

**Reference Ties:**

The corner falls 1' west of centerline of TH 63, in centerline of CSAH 6 west and 10.3' north of center of manhole
County Survey Disk in NE side PP SE 49.37'
Minnesota Highway Disk in NW side PP SW 99.79'
County Survey Disk in SE side PP NE 51.10'
This corner is located by GPS measurement

**Corner History:**

1853 Gov't. Notes: West on south boundary of Section 34 40.00 chs. Set quarter section post with trench Burr Oak 10 in. N81°E 235 lks.

6-8-1892 Thomas Fraser (Book A, P487 No. 413) County Surveyor, states corner gone and bearing tree gone. Set a stake between Northwest corner section 2 and the Northeast Corner of the Northwest Quarter section 2 and 5.63 chains east of the Northwest corner section 2.

10-10-1898 W. Fraser found and used stone monument for Brin's Plat.

5-1902 William Fraser (Book B, Page 16) County Surveyor, found stone set as corner. Measured west to Northwest corner section 2 (a stone found) and east to south section corner 34-35 (a stone found).

9-22-1917 C. Armstrong found and used stone monument for Halls Addition.

8-7-1974 Roger Brand, County Surveyor, reset corner at platted distance of 399.0' from the east (Hall's Addition - stone was found) and on line between the North Quarter Corner Section 2 and Northwest Corner Section 2. Set a cast iron monument over a 5/8" x 12" rod flush with bituminous surface of T.H. 63. Minnesota Highway Department notes call for a deep subcut here prior to grading so didn't dig for corner. RPs-CSD disc on NE side pp SE 45.94, top center of water hydrant NE 81.13, MHD disc on NW side pp SW 99.80, N end of radius on back side of curb NNW 57.90, 1" bolt on SW corner of lightpole base NNE 52.63.

8-24-1992 Yaggy Colby Associates found a cast iron monument set by Roger Brand 8-7-74 with the top broken off 0.5' below bituminous surface on T.H. 63. Corner falls 2.5' west and 1.0' south of the center lines of T.H. 63 and C.S.A.H. 6.

1-22-2002 County survey crew found corner gone due to T.H. 63 construction. Set 1" sq pipe w/cap at surface from 1992 Yaggy Colby traverse data.

7-11-2006 County survey crew found 1" square pipe w/o cap at surface disturbed by blacktop milling of TH 63. Removed 1" square pipe.

7-2-2007 County survey crew set 1" square pipe w/cap at surface from previously measured coordinates. Updated ties.

5-19-2016 County survey crew found MNDOT survey marker nail at the surface in good condition. Measured a check shot using GPS and verified the nail location matched previous measurements.