Certificate of Location of Government Corner

ID#: 543406 **Description:** 1/4 SEC COR 33 34 54 **Date Set:** 10/4/2007 **County:** Olmsted

Section: 34 **Township:** 105N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in line with E-W fence and in line with fence south
Post w/sign 2' west
This corner is located by GPS reference stations "Cemetery A & B"

Corner History:

1853 Gov't Notes 40.00 chs. Set 1/4 section post. Burr Oak 10 in. N48°W 72 lks. Burr Oak 10 in. S42°E 132 lks.

6-1892 T. Fraser P487 No. 413, Stewert Morse found stake in ground which agreed with nothwest bearing tree. Set limestone as corner.

10-1904 C. Armstrong P94B McCall, Stewert found limestone with cross as corner.

3-1954 McGhie found limestone 3.0' west of corner fence post.

10-1973 County Surveyor corner now same limestone (8" ± square, quite long), now just northwest of concreted in corner post of cyclone fence.

12-9-1992 Yaggy Colby Associates found same 8" square limestone 0.8' below the surface. Limestone falls in between concreted chain link fence posts. One post is a corner post with the fence running south and west, the other post is the end of a fence running east. Yaggy Colby Associates set a 3/4" iron pipe 0.70' east of the limestone as a reference monument.

11-9-2001 County Surveyor found 8" square limestone down 0.5' in good condition.

1-14-2002 County Surveyor set drill hole in limestone.

10-4-2007 County Surveyor found 8"x8"x29" limestone down 0.5' in good condition. Removed stone and set 6' telspar pipe w/cast iron cap down 0.1'.